

PRODUCT CHANGE NOTICE

Data Sheet Specification Change for Intersil ISL54206A* Product

Refer to: PCN10078

Date: July 22, 2010



July 22, 2010

To: Our Valued Intersil Customers

Subject: Data Sheet Specification Change for Intersil ISL54206A* Product

This notice is to inform you that Intersil has updated the data sheet specification for the listed ISL54206A* products. The changes align the data sheet with the product characteristics and are necessary to maintain product manufacturability in support of customer delivery requirements. Modifications to the data sheet specification are complete. The updated data sheet is available on the Intersil web site at http://www.intersil.com/data/fn/fn6515.pdf.

Products affected: ISL54206AIRTZ ISL54206AIRTZ-T ISL54206AIRUZ-T

Data Sheet specification changes are as follows:

| Thermal Information | | | | | | | | |
|--|---------------|-----------------------|-----------|-----|------------|-----|-------|---------|
| Thermal Resistance | θJA(°C/W) | | θJC(°C/W) | | | | | |
| | Current | New | Current | New | | | | |
| 10 ld μTQFN | 130 | 145 | - | 90 | | | | |
| 10 ld TDFN | 110 | 55 | - | 16 | | | | |
| Electrical Specifications | | | | | • | | | |
| Parameter | Temp | Current Limits | | | New Limits | | | I Inita |
| | (° C) | N/1: | Trm | Max | Min | Тур | Max | Units |
| | (C) | Min | Typ | Max | 141111 | ryp | IVIAX | |
| ON Looks as Cumant I | 25 | -10 | 2 | 10 | -30 | 8 | 30 | |
| ON Leakage Current, I _{DX} | ` ' | | | | | | | - A |
| ON Leakage Current, I _{DX} Positive Supply Current, | 25 | -10 | 2 | 10 | -30 | 8 | 30 | nA |

There will be no change in external marking of the packaged parts. Parts affected by this change are identifiable via Intersil's internal traceability system.

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product electrically screened to the revised limit beginning *ninety* days from the date of this notification or earlier with approval.

If you have concerns with this change notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Intersil Corporation PCN10078