

---

# **PRODUCT CHANGE NOTICE**

**Part Marking Configuration  
Change for Intersil TDFN,  
uTDFN, and uTQFN  
Packaged Products**

**Refer to:  
PA10114**

**Date: November 10, 2010**

November 10, 2010

To: Our Valued Intersil Customers

**Subject: Part Marking Configuration Change for Intersil TDFN, uTDFN, and uTQFN Packaged Products**

This notice is to inform you that Intersil is changing the configuration of the “top side” marking (brand) for the listed TDFN (Thin Dual Flat No-lead), uTDFN (Ultra Thin Dual Flat No-lead), and uTQFN (Ultra Thin Quad Flat No-lead) plastic packaged products. The restructured layout allows for the marking of additional characters in support of enhancing product traceability. There will be no change to the product code that is currently marked on the device. Examples of the current and new marking configurations are included for reference.

Product affected:

<b>Intersil Part Number - POD 1.2X1.0 - Single Digit Part Code</b>			
ISL54051IRUZ-T	ISL54054IRUZ-T	ISL54501IRUZ-T	ISL54504IRUZ-T
ISL54052IRUZ-T	ISL54055IRUZ-T	ISL54502IRUZ-T	ISL54505IRUZ-T
ISL54053IRUZ-T	ISL54500IRUZ-T	ISL54503IRUZ-T	
<b>Intersil Part Number - POD 1.4X1.2 - Two Digit Part Code</b>			
ISL54226IRUZ-T	ISL54226IRUZ-T7A	ISL54228IRUZ-T	ISL54228IRUZ-T7A
<b>Intersil Part Number - POD 1.6X1.6 - Single Digit Part Code</b>			
ISL9003AIRUBZ-T	ISL9003AIRUJZ-T	ISL9008AIRUBZ-T	ISL9008AIRUJZ-T
ISL9003AIRUCZ-T	ISL9003AIRUKZ-T	ISL9008AIRUCZ-T	ISL9008AIRUKZ-T
ISL9003AIRUFZ-T	ISL9003AIRUMZ-T	ISL9008AIRUFZ-T	ISL9008AIRUMZ-T
ISL9003AIRUHZ-T	ISL9003AIRUNZ-T	ISL9008AIRUHZ-T	ISL9008AIRUNZ-T
<b>Intersil Part Number - POD 1.6X1.6 - Two Digit Part Code</b>			
ISL28133FRUZ-T7	ISL9016IRUJCZ-T	ISL9021IRUFZ-T	ISL9103IRUCZ-T
ISL28190FRUZ-T7	ISL9016IRUJJZ-T	ISL9021IRUGZ-T	ISL9103IRUDZ-T
ISL28191FRUZ-T7	ISL9016IRUJWZ-T	ISL9021IRUJZ-T	ISL9103IRUFZ-T
ISL28194FRUZ-T7	ISL9016IRUKFZ-T	ISL9021IRUKZ-T	ISL9103IRUJZ-T
ISL28195FRUZ-T7	ISL9016IRUKKZ-T	ISL9021IRUMZ-T	ISL9103IRUNZ-T
ISL28196FRUZ-T7	ISL9016IRUKWZ-T	ISL9021IRUNZ-T	ISL9103IRUWZ-T
ISL28197FRUZ-T7	ISL9016IRUMBZ-T	ISL9021IRUPZ-T	ISL9104AIRUAZ-T
ISL55016IRTZ-T7	ISL9016IRUMCZ-T	ISL9021IRURZ-T	ISL9104AIRUBZ-T
ISL9003AIRURZ-T	ISL9016IRUMKZ-T	ISL9021IRUSZ-T	ISL9104AIRUCZ-T
ISL9016IRUBBZ-T	ISL9016IRUMWZ-T	ISL9021IRUTZ-T	ISL9104AIRUDZ-T
ISL9016IRUBWZ-T	ISL9016IRUNCZ-T	ISL9021IRUWZ-T	ISL9104AIRUFZ-T
ISL9016IRUCBZ-T	ISL9016IRUNWZ-T	ISL9021IRUYZ-T	ISL9104AIRUJZ-T
ISL9016IRUCCZ-T	ISL9016IRUWCZ-T	ISL9103AIRUAZ-T	ISL9104AIRUNZ-T
ISL9016IRUCWZ-T	ISL9016IRUWGZ-T	ISL9103AIRUBZ-T	ISL9104AIRUWZ-T
ISL9016IRUFBZ-T	ISL9016IRUWJZ-T	ISL9103AIRUCZ-T	ISL9104IRUAZ-T
ISL9016IRUFCZ-T	ISL9016IRUWKZ-T	ISL9103AIRUDZ-T	ISL9104IRUBZ-T

<b>Intersil Part Number - POD 1.6X1.6 - Two Digit Part Code - cont.</b>			
ISL9016IRUFFZ-T	ISL9021IRU1Z-T	ISL9103AIRUFZ-T	ISL9104IRUCZ-T
ISL9016IRUFWZ-T	ISL9021IRU2Z-T	ISL9103AIRUJZ-T	ISL9104IRUDZ-T
ISL9016IRUGCZ-T	ISL9021IRU3Z-T	ISL9103AIRUNZ-T	ISL9104IRUFZ-T
ISL9016IRUGGZ-T	ISL9021IRU4Z-T	ISL9103AIRUWZ-T	ISL9104IRUJZ-T
ISL9016IRUGWZ-T	ISL9021IRUBZ-T	ISL9103IRUAZ-T	ISL9104IRUNZ-T
ISL9016IRUJBZ-T	ISL9021IRUCZ-T	ISL9103IRUBZ-T	ISL9104IRUWZ-T
<b>Intersil Part Number - POD 1.8X1.4 - Single Digit Part Code</b>			
ISL28290FRUZ-T7	ISL54050IRUZ-T	ISL54062IRUZ-T	ISL54222AIRUZ-T
ISL28291FRUZ-T7	ISL54050IRUZ-T7A	ISL54066IRUZ-T	ISL54406IRUZ-T
ISL54047IRUZ-T	ISL54059IRUZ-T	ISL54210IRUZ-T	
ISL54048IRUZ-T	ISL54060IRUZ-T	ISL54211IRUZ-T	
ISL54049IRUZ-T	ISL54061IRUZ-T	ISL54220IRUZ-T	
<b>Intersil Part Number - POD 1.8X1.4 - Two Digit Part Code</b>			
ISL54063IRUZ-T	ISL54224IRUZ-T	ISL54225IRUZ-T7A	ISL54409IRUZ-T
ISL54064IRUZ-T	ISL54224IRUZ-T7A	ISL54227IRUZ-T	ISL54410IRUZ-T
ISL54209IRU1Z-T	ISL54225IRUZ-T	ISL54227IRUZ-T7A	

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product marked in accordance with either the current or new layout beginning ninety days from the date of this notification or until the depletion of existing inventory.

If you have concerns with this change notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*


Jon Brewster  
Intersil Corporation

PCN10114


CC: J. Touvell F. Cheng S. Ang S. Nadarajah T. Peterson

## PCN10114 – Marking Layout Examples

### POD 1.2 x 1.0 - Single Digit Part Code




### POD 1.4 x 1.2 - Two Digit Part Code




## PCN10114 – Marking Layout Examples– cont.

### POD 1.6 x 1.6 - Single Digit Part Code




### POD 1.6 x 1.6 - Two Digit Part Code



## PCN10114 – Marking Layout Examples– cont.

### POD 1.8 x 1.4 - Single Digit Part Code



### POD 1.8 x 1.4 - Two Digit Part Code

