

PRODUCT CHANGE NOTICE

Package Orientation Change for Tray Packing of the Listed Intersil Products

Refer to: PCN12066

Date: August 8, 2012

INTERSIL CORPORATION | 1650 Robert J. Conlan Blvd. | Palm Bay, FL USA 32905 | Telephone 321-724-7000 | www.intersil.com



August 8, 2012

To: Our Valued Intersil Customers

Subject: Package Orientation Change for Tray Packing of the Listed Intersil Products

This notice is to inform you that Intersil is changing the package orientation for tray packing of the listed QFN (Quad Flat No-Lead) plastic packaged products. The change in package orientation aligns pin 1 of the device with the tray chamfer/notch and is in accordance with established industry standards for packing of IC products. Diagrams depicting the changes in package orientation are included on the next page for reference. There will be no change in the trays (i.e. dimensions, materials, appearance, etc.) used for product shipment.

Products affected:

ISL8200MIRZ ISL8201MIRZ ISL8204MIRZ ISL8206MIRZ

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products. Customers may expect to receive shipments of the listed products packed in trays using the new orientation beginning ninety days from the date of this notification.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,

Jon Brewster

Jon Brewster Intersil Corporation

PCN12066

CC: J. McNamara C. Toh H. Li G. Parker N. Anantharajah

Package Orientation Diagram – PCN12066

Products ISL8200MIRZ

From





intersil

Products ISL8201MIRZ, ISL8204MIRZ, and ISL8206MIRZ

From

