

PRODUCT ADVISORY

Data Sheet Specification Change for Intersil ISL35111* Product

**Refer to:
PA10008**

Date: January 29, 2010

January 29, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil ISL35111* Product**

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL35111* products. The updates consist of the following:

- i) The descriptions were updated for the VDD and DE[A,B] pins in the Pin Descriptions table on sheet 2.
- ii) The Output Driver was updated to include the TDSBL pin in Figure 5 - Functional Block Diagram on sheet 5.
- iii) Added Figure 8 - Typical Application Reference Schematic and a section titled "PCB Layout Considerations" on sheet 7.

The updated data sheet, FN6975 dated January 27, 2010, is included as a separate attachment with the changes shaded in yellow.

Products Affected: **ISL35111DRZ-T7 ISL35111DRZ-TS**

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.



Jon Brewster
Intersil Corporation

PA10008

CC: J. Touvell E. Lee J. Mitchell M. Casino