

PRODUCT ADVISORY

Data Sheet Specification Change for Intersil Product ZL2106*

**Refer to:
PA11055**

Date: June 1, 2011

June 1, 2011

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product ZL2106***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ZL2106* products. The change to the range for the *High-Side Supply Voltage for BST Pin* in the Absolute Maximum Ratings section aligns the data sheet with the product characteristics. Modifications to the data sheet specification incorporating the changes are complete. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn6852.pdf>.

Products affected:

ZL2106ALCF	ZL2106ALCFT-01	ZL2106ALCN	ZL2106ALCNTR5451
ZL2106ALCF-01	ZL2106ALCFTK	ZL2106ALCNT	
ZL2106ALCFT	ZL2106ALCFTK-01	ZL2106ALCNTK	

The data sheet specification changes are as follows:

Absolute Maximum Ratings	Previous Range	New Range
High-Side Supply Voltage for BST Pin	-0.3V to 30V	-0.3V to 25V

There will be no change in external marking of the packaged parts. There have been no changes made to the silicon or device itself.

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster
Intersil Corporation

PA11055

CC: J. Touvell T. Wolter C. Young