

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
Renesas Technology Corp.

Product Category	MPU/MCU		Document No.	TN-SH7-A710A/E	Rev.	1.00
Title	The correction of the error in writing about Data Control Register (SPDCR) of Renesas Serial Peripheral Interface		Information Category	Technical Notification		
Applicable Product	SH7262 Group SH7264 Group	Lot No.	Reference Document	<ul style="list-style-type: none"> · SH7262 Group, SH7264 Group Hardware Manual (REJ09B0445-0100) 		
		ALL				

We would like to inform you the correction of the error in writing about Data Control Register (SPDCR) of Renesas Serial Peripheral Interface in upper product.

Before a revision

If the contents of SPDCR are changed while the SPE bit in the control register (SPCR) is 1 with the function of this module enabled in master mode, the subsequent operation cannot be guaranteed.

After a revision

If the contents of bits other than the TXDMY of SPDCR are changed while bit TEND in the status register (SPSR) indicates that transmission is not completed, the subsequent operation cannot be guaranteed.