

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

# RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan  
Renesas Technology Corp.

Product Category	MPU/MCU		Document No.	TN-SH7-A711A/E	Rev.	1.00
Title	The error correction about Electrical Characteristics/AC Characteristics/Bus Timing ( $t_{WDH1}$ , $t_{MAH}$ )		Information Category	Technical Notification		
Applicable Product	SH7262 Group SH7264 Group	Lot No.	Reference Document	SH7262 Group, SH7264 Group Hardware Manual (REJ09B0445-0100)		
		ALL				

We would like to inform you of the following error corrections of Electrical Characteristics/AC Characteristics/Bus Timing in the above-mentioned applicable products.

## Error correction

[Error]

Table 37.7 Bus Timing

Item	Symbol	Min.	Max.	Unit	Figure
:					
Write data hold time 1	$t_{WDH1}$	2	—	ns	37.9~37.15、37.36~37.39
:					
Multiplexed address hold time	$t_{MAH}$	2	—	ns	37.13
:					

[Correction]

Table 37.7 Bus Timing

Item	Symbol	Min.	Max.	Unit	Figure
:					
Write data hold time 1	$t_{WDH1}$	1	—	ns	37.9~37.15、37.36~37.39
:					
Multiplexed address hold time	$t_{MAH}$	1	—	ns	37.13
:					