

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

# RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan  
Renesas Technology Corp.

Product Category	MPU&MCU		Document No.	TN-SH7-A707A/E	Rev.	1.00
Title	The error correction about the format of the output data stream produced by CD-ROM decoding		Information Category	Technical Notification		
Applicable Product	SH7261 Group SH7263 Group	Lot No.	Reference Document	<ul style="list-style-type: none"> <li>• SH7261 Group Hardware Manual (REJ09B0320-0200)</li> <li>• SH7263 Group Hardware Manual (REJ09B0290-0200)</li> </ul>		
		ALL				

We would like to inform you of the following error corrections of CD-ROM Decoder included in the above-mentioned applicable products.

1. The portion of the hardware manual

- (1) SH7261 Group Page 1003 (21.4.5 Buffering Format)
- (2) SH7263 Group Page 1141 (21.4.5 Buffering Format)

2. Error correction

[Error]

FM: Indicates the data format

- 001: Mode 0
- 010: Mode 1
- 011: Long (format with no EDC and ECC)
- 100: Mode 2 (non-XA)
- 101: Mode 2 Form 1
- 111: Mode 2 Form 2

[Correction]

FM: Indicates the data format

- 001: Mode 0
- 010: Mode 1
- 011: Long (format with no EDC and ECC)
- 100: Mode 2 (non-XA)
- 101: Mode 2 Form 1
- 110: Mode 2 Form 2**