

CUSTOMER NOTIFICATION

SUD-T-5066-1-E
November 1, 2000
Yoichi Hirasawa, Expert Microcomputer Engineering Dept. Solution Engineering Div. NEC Electron Devices NEC Corporation

CP (K), O

IE-789436-NS-EM1
(Control Code: B)

Operating Precautions

Be sure to read this document before using the product.

1. PRODUCT VERSION 2
2. PRODUCT HISTORY 2
3. DETAILS OF BUGS AND ADDITIONS TO SPECIFICATION 2
4. OTHER CAUTIONS.....2

1. PRODUCT VERSION

Part number: IE-784936-NS-EM1

Control Code	Remark
A	μPD78F9436 Ver. 1.0
B	μPD78F9436 Ver. 1.0

Note The “control code” is the second digit from the left in the 10-digit serial number in the warranty supplied with the in-circuit emulator you purchased (if it has not been upgraded). If the in-circuit emulator has been upgraded, a label indicating the new version is attached to the in-circuit emulator and the x in V-UP LEVEL x on this label indicates the control code.

If you have any questions concerning the product, consult the Development Tool Support Center.

TEL (044) 435-9454

FAX (044) 435-9605

E-mail: toolsupport@saed.tmg.nec.co.jp

2. PRODUCT HISTORY

No.	Bugs and Changes/Additions to Specification	Control Code	
		A	B
1	Bug in booster operation for LCD function	√	—

√ : Applicable

— : Not applicable

3. DETAILS OF BUGS AND ADDITIONS TO SPECIFICATION

1. Bug in booster operation for LCD function

[Details] The LCD boost function does not operate normally when the LCD function is emulated.

Even if the voltage boost level is multiplied by 1.5 using the LCD boost control register (LCDVA0) when the booster is operating, COM and segment pins are only boosted up to the voltage level of the user power supply.

[Countermeasure] There is no temporary countermeasure.

4. OTHER CAUTIONS

None