

RENESAS TOOL NEWS on November 29, 2010: 101129/tn2

A Note on Using Flash Development Toolkit --Problem with Successively Programming Flash Memory by Using the E8a in the E8aDirect Mode--

When you use Flash Development Toolkit, take note of the following problem:

- With successively programming flash memory by using the E8a in the E8aDirect mode
-

1. Product and Versions Concerned

Flash Development Toolkit

V.4.05 Release 00 through V.4.06 Release 01

2. MCUs Involved

MCUs of SuperH RISC engine, H8SX, H8S, and H8 families

3. Description

If you program flash memory successively by using the E8a emulator in the E8aDirect mode, you may see the following error message on-screen and fail in programming:

Error No 15005: 'E8aDirect' read time out

If the above message is displayed, execute the Connect to Device command, erase the flash memory, and then reprogram it. However, you need not make another settings of the project and device.

If the above message is not displayed, and programming has been completed as usual, the result is successful.

4. Schedule of Fixing the Problem

We plan to fix this problem in V.4.07 Release 00, which is due to be published at the end of February 2011.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.