

[Notes]

R20TS0398EJ0100

Rev.1.0

Feb. 01, 2019

e² studio Code Generator Plug-in, AP4 Coding Assistance Tool for RZ

Outline

When using the products in the title, note the following point:

1. Point for caution regarding the write value of RSPI status register (SPSR)

1. Point for caution regarding the write value of RSPI status register (SPSR)

1.1 Applicable Products

- e² studio V4.0.0.26 (Code Generator Plug-in V2.0.0 and later)
- AP4 coding assistance tool for RZ V1.00.00

1.2 Applicable MCUs

- RZ family: RZ/T1 group

1.3 Details

When using the serial peripheral interface (RSPIa), unintended operation may occur due to an incorrect value set to the RSPI status register (SPSR).

For details, refer to the technical updates of the applicable MCU.

https://www.renesas.com/search/keyword-search.html#genre=document&q=TN-RZ*-A054A

RZ/T1Group User's Manual:

Restriction on the write value of the RSPI status register

Although the “void R_RSPIO_Start(void)” function in source file “r_cg_rspi.c” output by the applicable products sets the reserved bits of the SPSR register to 0, it has no effect on the operation as it is written when the SPE bit of the RSPI control register (SPCR) is 0 (RSPI function disabled).

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Feb. 01, 2019	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2019 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.2