

## Outline

When using Security Key Management Tool, note the following points.

1. Secure Factory Programming Function User Program Encryption Notes

## 1. Secure Factory Programming Function User Program Encryption Notes

### 1.1 Applicable Products

Security Key Management Tool V.1.05, V.1.06, V.1.07

### 1.2 Applicable Devices

RA Family

### 1.3 Details

RA Family some devices that support the Secure Factory Programming function have boot firmware that supports writing to external flash memory. However, Security Key Management Tool V.1.05, V.1.06, V.1.07 does not support encryption of images in the external flash memory area in the encryption function for using the Secure Factory Programming function.

When encrypting a file containing an image of an external flash memory area using Security Key Management Tool V.1.05, V.1.06, or V.1.07, the encryption completes without outputting an error, but the output file does not contain the encrypted external flash memory area.

### 1.4 Conditions

This problem occurs when a file containing an image of an external flash memory area is encrypted using the /encsfp command in the CLI version or the SFP tab in the Standalone or e<sup>2</sup>studio Plug-in versions.

### 1.5 Workaround

No workaround is available.

### 1.6 Schedule for Fixing the Problem

Encryption of external flash memory area will be supported in V.1.08. (Scheduled for Feb. 2025)

## Revision History

| Rev. | Date      | Description |                      |
|------|-----------|-------------|----------------------|
|      |           | Page        | Summary              |
| 1.00 | Jan.20.25 | -           | First edition issued |
|      |           |             |                      |

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

## Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

## Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

## Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)