

## The Emulator Software for the E10A-USB Emulators Revised to V.2.10 Release 00

The emulator software for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H) have been revised to V.2.10 Release 00. The emulator software and emulators are used to emulate systems designed with MCUs of the SuperH RISC engine, H8SX, and H8S families.

### 1. Products to Be Updated

Emulator software V1.0.00 through V.2.09 Release 00 for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H)

### 2. Description of Revision

The following devices have been added to the support line:

| Device Group | Devices   |
|--------------|---|
| SH-4A        | SH7730, SH77650,<br>SH77651   |
| SH-3         | SH7721  |
| H-2          | SH7136, SH7137  |
| H8SX         | H8SX/1668RF,<br>H8SX/1664RF,<br>H8SX/1663RF,<br>H8SX/1658RF,<br>H8SX/1654RF,<br>H8SX/1653RF |
| H8S          | 8S/2117RF   |

### 3. How to Update Yours

Free-of-charge online update is available using either of the following

methods.

(1) Use AutoUpdate Utility (available on and after November 9).

(2) Download the update program (a ZIP file) from the Web site at

[http://www.renesas.com/e10a\\_usb\\_download](http://www.renesas.com/e10a_usb_download)

(available on and after November 6); then decompress the downloaded ZIP file to obtain the install program (HewInstMan.exe file) and execute it.

#### **4. Notice**

If the install program in 3 (2) above is executed in the system where High-performance Embedded Workshop V.4.02 or earlier resides, the IDE will be updated to V.4.03.00.

---

#### **[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.