

[Upgrade to revision]

R20TS0393EJ0100

Rev.1.00

Jan. 16, 2019

CS+ Code Generator for RL78 (CS+ for CC),
CS+ Code Generator for RL78 (CS+ for CA,CX),
e² studio Code Generator Plug-in,
AP4 Coding Assistance Tool for RL78,
Applilet3 Coding Assistance Tool for RL78

Outline

The products in the title have been updated as listed below.

- (1) CS+ Code Generator for RL78 (CS+ for CC): From V2.16.00 to V2.17.00
- (2) CS+ Code Generator for RL78 (CS+ for CA,CX): From V2.16.00 to V2.17.00
- (3) e² studio Code Generator Plug-in: From V2.11.0 to V2.12.0
- (4) AP4 Coding Assistance Tool for RL78: From V1.15.00 to V1.16.00
- (5) Applilet3 Coding Assistance Tool for RL78: From 1.15.00 to V1.16.00

1. Products and Versions to Be Updated

- CS+ Code Generator for RL78 (CS+ for CC) V2.16.00 and all earlier versions
- CS+ Code Generator for RL78 (CS+ for CA,CX) V2.16.00 and all earlier versions
- e² studio V7.2.0 (Code Generator plug-in V2.11.0) and all earlier versions
- AP4 Coding Assistance Tool for RL78 V1.15.00 and all earlier versions
- Applilet3 Coding Assistance Tool for RL78 V1.15.00 and all earlier versions

2. Main Features of Update

The main feature of the update is listed in section 2.1. For details, refer to the following release notes.

- CS+ Code Generator for RL78 (CS+ for CC) and CS+ Code Generator for RL78 (CS+ for CA,CX)
CS+ Code Generator for RL78 (CS+ for CC), (CS+ for CA,CX) V2.17.00 Release Note
(Scheduled to be released on January 21.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4473>
- e² studio Code Generator Plug-in
e² studio V7.3.0 Release Note (Scheduled to be released on January 21.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4471>
- AP4 Coding Assistance Tool for RL78
AP4 for RL V1.16.00 Release Note (Scheduled to be released on January 21.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4474>
- Applilet3 Coding Assistance Tool for RL78
Applilet3 for RL78 V1.16.00 Release Note (Scheduled to be released on January 21.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4472>

2.1 Item Revised

The following problem has been fixed.

(1) RENESAS TOOLNEWS Document No. R20TS0370EJ0100

1. Setting Serial UART4

Applicable MCUs: RL78/I1A group

For details about this problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0370>

3. Updating Your Product

Updating method varies depending on the product you are using.

See the following for details. The updates are provided free of charge.

3.1 Updating CS+ Code Generator for RL78

For how to update CS+, refer to section 4, “Updating Your Product” in RENESAS TOOLNEWS, Document No. R20TS0384EJ0100. (Scheduled to be released on January 21.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0384>

3.2 Updating e² studio Code Generator Plug-in

For how to update e² studio, refer to section 3, “Updating Your Product” in RENESAS TOOLNEWS, Document No. R20TS0386EJ0100. (Scheduled to be released on January 21.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0386>

Note that you cannot update only the code generator plug-in.

3.3 Updating AP4 and Applilet3 Coding Assistance Tool for RL78

Download the installer from the following URL for an installation. (Scheduled to be released on January 21.)

https://www.renesas.com/applilet_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jan. 16, 2019	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
 Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.