

[Upgrade to Revision]

R20TS0976EJ0100

Rev.1.00

Oct. 16, 2023

e² studio RL78 Smart Configurator Plug-in V1.8.0

Smart Configurator for RL78 V1.8.0

Outline

The products in the title have been updated as follows.

- (1) e² studio RL78 Smart Configurator Plug-in: From V1.7.0 to V1.8.0
- (2) Smart Configurator for RL78: From V1.7.0 to V1.8.0

1. Products to Be Updated

- e² studio 2023-07 (Smart Configurator Plug-in V1.7.0)
- Smart Configurator for RL78 V1.7.0

2. Description

The following issue has been fixed.

- 1. Fixed the issue of middle-speed on-chip oscillator is not reflected to fIMP in [Clocks] page.

For other fixes, please refer to the release notes above.

- Smart Configurator for RL78
Smart Configurator for RL78 V1.8.0 Release Note (the note will be uploaded on October 20)
<https://www.renesas.com/software-tool/rl78-smart-configurator#documents>

3. Updating the Product

Refer to the following and update accordingly. The products can be updated free of charge.

3.1 e² studio

Refer to the Tool News (3. Updating the Product) at the URL below (the news will be uploaded on October 20).

<https://www.renesas.com/software-tool/e-studio#documents>

RENESAS TOOL NEWS: R20TS0968EJ0100 (October 16, 2023, issue)

[Upgrade to Version] e² studio Integrated Development Environment 2023-10

Note: The Smart Configurator is updated automatically when e² studio is updated.

3.2 CS+

Download the latest Smart Configurator for RL78 from the URL below and install it (V1.8.0 will be released on October 20).

<https://www.renesas.com/software-tool/smart-configurator#download>

Smart Configurator for RL78 V1.8.0

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/