

[Upgrade to Revision]

R20TS0957EJ0100

Rev.1.00

Jul. 16, 2023

e² studio Smart Configurator Plug-in V2.18.0,
Smart Configurator for RX V2.18.0

Outline

The products in the title have been updated as follows.

- (1) e² studio Smart Configurator Plug-in: From V2.17.0 to V2.18.0
- (2) Smart Configurator for RX: From V2.17.0 to V2.18.0

1. Products to Be Updated

- e² studio 2023-04 (Smart Configurator Plug-in V2.17.0) and earlier
- Smart Configurator for RX V2.17.0 and earlier

2. Description

The following issue has been fixed.

- When using SCI/SCIF Clock Synchronous Mode component, SCMR.CHR1 bit is being configured as 1 instead of 0 after code generation. This issue has been fixed.
- After adding the Port Output Enable (POE) component from the "Component" page, its GUI configuration may not be displayed in the Smart Configurator. This issue has been fixed.
- After changing the SU section to 0x00000000 in the CS+ project and generating code in the Standalone Smart Configurator, the following section error will be displayed. This issue has been fixed.

For other fixes, please refer to the release notes above.

- Smart Configurator for RX
Smart Configurator for RX V2.18.0 Release Note (the note will be uploaded on July 20)
<https://www.renesas.com/software-tool/rx-smart-configurator#documents>

3. Updating the Product

3.1 e² studio

Refer to the following tool news (section 3, Updating the Product) in the link below. (The news will be uploaded on July 20th, 2023.)

<https://www.renesas.com/software-tool/e-studio>

RENESAS TOOL NEWS: R20TS0950EJ0100

[Upgrade to Version] e² studio Integrated Development Environment 2023-07

Note: The Smart Configurator is updated when the e² studio is updated.

3.2 CS+

Download the Smart Configurator for RX from the link below and install it. (It will be uploaded on July 20th, 2023.)

<https://www.renesas.com/rx-smart-configurator#downloads>

Smart Configurator for RX V2.18.0

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/