
**[Upgrade to Revision]
License Manager V2.09.00 (for Windows)**

R20TS1182EJ0100
Rev.1.00
2025.10.20

Outline

License Manager has been updated from V2.08.00 (for Windows) to V2.09.00 (for Windows).

1. Products to Be Updated

License Manager V1.00.00 to V2.08.00 (for Windows)

2. Description

The main changes are as follows. Refer to the release note for details.

<https://www.renesas.com/rl78-c-documentation>

<https://www.renesas.com/rx-c-documentation>

<https://www.renesas.com/rh850-c-documentation>

2.1 Updating the operating environment

The software environment for the license manager has been updated.

The runtime library version has been updated to:

Microsoft .NET Framework 4.8

2.2 Changes to the floating license (offline mode)

The following features have been added to the offline mode of floating licenses to improve their operation:

- When obtaining a floating license in offline mode, the license manager now displays the current floating license usage status.
Note: This function requires the Software for floating license management V2.09.00 or later on the server PC.
- Improved so that if a floating license acquired in offline mode is forcibly terminated by the Software for floating license management, the license will also be invalidated on the license manager side.

2.3 Fix for error (E0172009) when starting the license manager

Fixed an issue where License Manager V2.08.00 (Windows) could not be started due to error E0172009.

3. Updating the Product

3.1 Online Update

Start the update manager from [Renesas Electronics CS+] in the Windows start menu and update.

3.2 Downloading the Installer

Download the installer from the URL below.

<https://www.renesas.com/rl78-c-download>

<https://www.renesas.com/rx-c-download>

<https://www.renesas.com/rh850-c-download>

Software for floating license management V2.09.00 can also be downloaded from the above URL.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.20.25	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/