

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RA*-A0001A/E	Rev.	1.00
Title	Errata for User's Manual: Hardware regarding the overview		Information Category	Technical Notification		
Applicable Product	RA2A1 Group	Lot No.	Reference Document	RA2A1 Group User's Manual: Hardware Rev.1.00		
		All				

The specified RA2A1 User's Manual: Hardware has incorrect statements about the overview.

Page 50 of 1282

Table 1.7 Communication interface (2 of 2)

USB 2.0 Full-Speed (USB-FS) module

#### Incorrect

The USB 2.0 Full-Speed (USBFS) module can operate as a **host controller or** device controller.

#### Correct

The USB 2.0 Full-Speed (USBFS) module can operate as a device controller.