RENESAS Tool News

RENESAS TOOL NEWS on October 16, 2003: RSO-M3T-NC308WA_2-031016D

A Note on Using C Compilers M3T-NC308WA and M3T-NC30WA

Please take note of the following problem in using the M3T-NC308WA and M3T-NC30WA C compilers (with an assembler and integrated development environment):

• On the division and remainder operations between constants

1. Products and Versions Concerned

The M3T-NC308WA V.5.00 Release 1 and V.5.10 Release 1 for the M32C/80 and M16C/80 series

The M3T-NC30WA V.5.00 Release 1 through V.5.20 Release 1 for the M16C/60, M16C/30, M16C/Tiny, M16C/20, M16C/10, and R8C/Tiny series

2. Description

A division or remainder operation between constants may results in an error.

2.1 Conditions

This problem occurs if the following three conditions are satisfied:

- (1) In the program exists an expression containing a division or remainder operation between constants.
- (2) Either the dividend or the divisor of the division or remainder operation is of type signed long long or unsigned long long.
- (3) The upper 32 bits of the dividend is neither 0 nor 0xffffffff.
- 2.2 Example

long long l;

main()

3. Workaround

Replace the expression of the division or remainder operation with its result.

```
long long l;
main()
{
    I = 100000000; /* Replaced with the result of division */
}
```

4. Schedule of Fixing the Problem

We plan to fix this problem in our next release of the products.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.