

RENESAS TOOL NEWS on May 16, 2008: 080516/tn4

A Note on Using Flash Development Toolkit

Please take note of the problem described below in using Flash Development Toolkit.

1. Product and Versions Concerned and MCUs Involved

(1) Product and versions concerned

Flash development Toolkit V.4.00 Release 00 through V.4.01 Release 01

(2) MCUs involved

All the MCUs of the SuperH RISC engine, H8SX, H8S, and H8 families

2. Problem

If the "connect" script command takes "E8aDirect" and the serial number of your E8a emulator (USB BID) as its arguments, the Select USB Device dialog box will appear in spite of the fact that it would not be allowed to do so.

3. Workaround

In the Select USB Device dialog box that appears, select the serial number of your E8a emulator and click the OK button.

4. Schedule of Fixing the Problem

We plan to fix this problem in the V.4.02 Release 00 product.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.