

Note on Using Integrated Development Environment e2 studio V3.0 or V3.1

Using the e2 studio V3.0 or V3.1, take note of the following problems:

- Note when debugging with e2 studio
-

1. Product Concerned

- e2 studio V3.0.0.22, V3.0.1.07, V3.0.1.08, V3.0.1.09, and V3.1.0.24

2. MCUs Involved

RX family

3. Description

3.1 Data type description in Expression View after data type has been modified and rebuilt, previous data type may be shown in the view while the values are correctly updated.

3.2 Renesas Profile View after disconnect and re-connect debug session, values may not be shown in the view.

4. Workaround

4.1 Workaround for 3.1

Please perform a "clean" and rebuild of the project if you encounter this issue.

4.2 Workaround for 3.2

Renesas Profile View after disconnect and re-connect debug session, please restart e2 studio then connect debug session again if you encounter this issue.

5. Fixing the Problem

These problems have been fixed in version V3.1.1.08 of e2 studio to be available from Nov 7 as announced in RENESAS TOOL NEWS Doc No.141107/tn2.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=141107tn2>

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.