

RENESAS TOOL NEWS on August 16, 2010: 100816/tn1

H8SX E100 Emulator Software Revised to V.1.01 Release 00

We have revised H8SX E100 Emulator Software from V.1.00 Release 01 to V.1.01 Release 00.

H8SX E100 Emulator Software is bundled with MCU unit R0E417250MCU00.

For an overview of the product, go to <https://www.renesas.com/e100> and click "Debug Functions" on the "E100" menu at the upper left of the page.

For an overview of MCU unit R0E417250MCU00, go to

<https://www.renesas.com/products/software-tools/tools/emulator/e100--r0e417250mcu00.html>

The above URLs are those of our global sites.

1. Product to Be Updated

H8SX E100 Emulator Software V.1.00 Release 01

2. Description of Revision

The problem with using M16C R8C E100 Emulator Software or H8SX E100 Emulator Software in combination with High-performance Embedded Workshop V.4.06.00 or later on Windows Vista(R) has been fixed.

For details see RENESAS TOOL NEWS Document No. 090916/tn3 at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=090916tn3>

3. How to Update Your Product

Online update is available free of charge. Update yours in either of the following ways:

(1) Use AutoUpdate Utility. This service is available on and after August 20.

(2) Download the update program of the revised product from:

https://www.renesas.com/e100_download

Then execute it. This site will be opened from August 20 on.

The above URL is one of our global sites.

NOTICE:

If the above update program is executed in the system where High-performance Embedded Workshop V.4.07.00 or earlier resides, it will be upgraded to V.4.07.01.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.