

RENESAS TOOL NEWS on June 16, 2012: 120616/tn2

High-performance Embedded Workshop Revised to V.4.09.01

We have revised High-performance Embedded Workshop from V.4.09.00 to V.4.09.01. High-performance Embedded Workshop is included with the compilers, emulator debuggers, and other software products that it manages. For details of the product, go to:

<https://www.renesas.com/hew>

The above URL is one of global sites.

1. Your Products to Be Updated

High-performance Embedded Workshop V.3.00.00 through V.4.09.00

To check to see the version number of your High-performance Embedded Workshop, open the Help menu and select the About High-performance Embedded Workshop command.

2. Descriptions of Revision

2.1 Problems Fixed

The following problems have been fixed:

(1) The problem reported in RENESAS TOOL NEWS Document No. 111001/tn1:

- With using Real-time OS aware debugging function

For details, see the above document at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=111001tn1>

(2) The problem relating to the question stated in FAQ No. 1009867:

- When I try to generate a makefile in the High-performance Embedded Workshop, the makefile is not generated and the makefile generator program will not terminate.

For details, see the FAQ on the Web page at:

<https://en-eu.knowledgebase.renesas.com/Special:Search?tags=FAQNo%3A1009867>

(3) The problem reported in RENESAS TOOL NEWS Document No. 120416/tn2:

- With executing builds

For details, see the above document at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=120416tn2>

(4) The problem reported in RENESAS TOOL NEWS Document No. 120601/tn3:

- With executing builds

For details, see the above document at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=120601tn3>

2.2 Capability Improved

When High-performance Embedded Workshop V.4.08.00 or later is used together with the following products, the time necessary for expressing the C0/C1 coverage as a percentage, saving coverage information, and searching for the unexecuted lines has been reduced:

- E100 Emulator Software
- E200F Emulator Software
- AE-5 E6000H Emulator Software
- AE-4 E6000 Emulator Software

3. Updating Your Product

Online update is available free of charge. To update yours, do either of the following:

(1) Use AutoUpdate Utility. This service will be available on and after June 25, 2012.

(2) Download the update program of the product at:

https://www.renesas.com/hew_download

Then execute it. The update program will be published on this site on this June 20.

The above URL is one of our global sites.

NOTES:

Two types of update program are available. Use either of them as necessary. They are as follows:

(a) Full update program

The components of High-performance Embedded Workshop to which changes have been made in and after V.3.00.00 are updated; that is, V.3.00.00 through V.4.09.00 can be updated.

(b) Differential update program

The components of High-performance Embedded Workshop to which changes have been made in and after V.4.09.00 are updated;

that is, V.4.09.00 can be updated.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.