

November 11, 2014

To: Our Valued Customers

Attention: Procurement Manager

Subject: PLC14051D – Product Discontinuance / Obsolescence Notification

Product discontinuance notice, PLC14051A contained a product that should NOT have been included in the list of Intersil devices being put into the end of life cycle process. The following product has been removed from the notice and are active for procurement. Intersil will continue to produce these devices for the foreseeable future. For any questions regarding the availability of these devices, please contact your local Intersil Sales person.

Product List:

ISL32173EFVZ ISL32173EFVZ-T

The table in Appendix has been updated to include only the parts that should be in the end of life process.

You are hereby provided notice that the Intersil products included on the attached parts list (appendix) are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the list and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

PLC14051D

CC: J. Rye S. Gupta M. Bennett R. Pitts



Appendix

Exact Intersil Part # No other variation is being impacted.	Notice PLC14051 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
CD4047BDMSR	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
CD4047BHSR	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
CD4047BKMSR	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
CD4047BKNSR	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
ISL32374EIVZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL32172EFVZ
ISL3282EMRTEP-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL3298EMRTEP-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL3298EMRTEP
ISL4486IUZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL51002CQZ-110	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL51002CQZ-165
ISL51002CQZ-150	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL51002CQZ-165
ISL59118IRUZ-T7	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL59121IIZ-T7	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6208ACBZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6217CVZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6217CVZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6251HRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6251AHRZ
ISL6258AHRTZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6258HRTZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6258HRTZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6260CCRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6263CHRZ	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
ISL6266AHRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6266AHRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6308ACRZ-TR5609	19-Sep-2014	19-Mar-2015	19-Sep-2015	ISL6308ACRZ
ISL6323BCRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6323BCRZR5381	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6323BCRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6323BCRZ-TR5381	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6323CRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6323CRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6334ACRZ-TR5368	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6334BCRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6405ERZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6420AIRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6420BIRZ
ISL6420BMAEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6420IRZ
ISL6420BMAEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6420IRZ
ISL6423BEVEZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6423BERZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC14051 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6441IRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6442IAZ
ISL6441IRZ-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6442IAZ
ISL6535CBZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6535IRZ
ISL6535CBZ-TR5453	19-Sep-2014	19-Mar-2015	19-Sep-2015	ISL6535IRZ
ISL6535CRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6535IRZ
ISL65426MREPZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL65426HRZ
ISL65426MREPZ-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL65426HRZ
ISL6549CAZA-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6549IBZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6549IBZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6566ACRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6566CRZ-TR5184	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6568CRZ-TR5184	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6612AIRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6614BCRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6614CRZ
ISL6616AW	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
ISL6616AWR5375	19-Sep-2014	19-Mar-2015	19-Sep-2015	None
ISL6721ABZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6721AVZ
ISL6729IBZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL6740IVZ-TS2462	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6740AIVZA
ISL6745AUZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL6745AAUZ
ISL6845IUZ-T	19-Sep-2014	19-Mar-2015	19-Sep-2015	ISL8845AAUZ
ISL8105BCBZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8105IBZ
ISL8105BCBZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8105IBZ
ISL8105BCRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8105IRZ
ISL8105BIBZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8120CRZ-TR5468	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8120IRZ
ISL8501IRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8510IRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8702AIBZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8702IBZ
ISL8840AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8840AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8841AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8841AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8842AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8842AMBZ
ISL8842AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8842AMBZ
ISL8843AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8843AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8844AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8844AMBZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC14051 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL8844AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL8844AMBZ
ISL8845AMBEP	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL8845AMBEP-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL9214IRZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL9214AIRZ
ISL9443IRZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL9444IRZ
ISL9519QHRTZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL97631IHTZ-T7A	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL97634IRT18Z
ISL97632IRT26Z-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL97634IRT26Z
ISL97632IRT26Z-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	ISL97634IRT26Z
ISL97645IRZ-T	19-Sep-2014	19-Mar-2015	19-Sep-2015	ISL97645AIRZ
ISL97646IRZ-T	19-Sep-2014	19-Mar-2015	19-Sep-2015	ISL97645AIRZ
ISL97650ARTZ	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL97650ARTZ-T	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
ISL97650ARTZ-TK	19-Sep-2014	19-Sep-2015	19-Mar-2016	None
TW2864B-LC2-GR	19-Sep-2014	30-Nov-2014	19-Sep-2015	TW2864B-LD1-CR