

DA14682/683 Hardware Known Limitations

Family:	DA1468x			
Date:	29-May-18	©Dialog Semiconductor		
Item Nr	Date	Description	Solution/Workaround	Status
241	09-Nov-17	A spike on the input when you are still pressing a button, it will debounce it	Use debounce time greater than expect	Not fixed
		and go to the KEY_PRESSED state again, generating a duplicate KEYBR_IRQ	spike, A value of minimum 10 ms is a good	
			practical value	