
[Notes]

R20TS0589EJ0100

Rev.1.00

Jun. 16, 2020

On-chip Debugging Emulator

E2 Emulator

Outline

When using the E2 on-chip debugging emulator, note the following point.

1. Using E2 emulator for the RL78 family

1. Using E2 Emulator for the RL78 family

1.1 Applicable Products

- E2 Emulator

This problem occurs when using the above emulator with the following devices and integrated development environments.

- Applicable devices: RL78 family (except RL78/G10 group)
- Applicable integrated development environments: CS+, e² studio, and IAR Embedded Workbench for Renesas RL78

1.2 Details and Conditions

If a break occurs during self programming, the debugger hangs up and cannot continue debugging.

1.3 Workaround

In a program that uses the self-programming function, set breakpoints before or after using the self-programming function.

1.4 Schedule for Fixing the Problem

This problem will be fixed in the next version of each integrated development environment.
(Scheduled to be released in January 2021 or later.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jun.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.