

INTERSIL CORPORATION
1650 Robert J. Conlan Blvd.
Palm Bay, FL 32905

January 29, 2014

Dear Customer:

This communication is to inform you of a decision by the United States export authorities that has resulted in the transfer of the listed Intersil Corporation radiation tolerant/space compatible products to the export jurisdiction of the US Department of State. Intersil Corporation is questioning the 'broad brush' nature of the decision and is in the process of preparing formal Commodity Jurisdiction (CJ) requests to have our products returned to the jurisdiction of the Department of Commerce, as they have been previously. We will provide you with any changes to this situation as soon as they arise. Intersil considers this jurisdictional transfer to be effective as of January 31, 2014.

However, until Intersil can get a favorable ruling in this matter, our radiation tolerant/space compatible products will require export licenses from the Department of State for all direct sales to customers outside of the United States.

For further information, below is a summary of directions Intersil Corporation received from the US Directorate of Defense Trade Control:

1. For any components which **HAVE** already been exported under EAR jurisdiction, these components **ARE** retroactively subject to the retransfer/re-export provisions of 22 CFR 123.9.
2. For any components which **HAVE NOT** already been exported (directly by Intersil or by one of its US customers), based on Intersil's prudent self-determination to treat them as ITAR-controlled effective January 31, 2014, exports from the US will require an export license. Such export licenses must follow the requirements of 22 CFR 123 and supplemental guidance found on the Department of State website at www.pmddtc.state.gov. All permanent exports must be supported with purchase documentation (purchase order or contract) from a foreign party on the license which is addressed to the license applicant. Licenses also require an end-use statement from the foreign party.

If you have any questions please contact me at 321/724-7103 or hgeorge@intersil.com

Best Regards,

Henry George Jr.
Trade Compliance Manager

Products Affected

Intersil Part Number	DLA SMD Part Number	Intersil Part Number	DLA SMD Part Number
HS0-0546RH-Q	5962D9569301V9A	HS9-5104ARH-T	5962R9569001TXC
HS0-0547RH-Q	5962D9569302V9A	HS9-OP470AEH-Q	5962R9853302VXC
HS0-1100RH/SAMPLE	N/A	HS9-OP470ARH/PROTO	N/A
HS0-1100RH-Q	5962F9467602V9A	HS9-OP470ARH-8	5962R9853301QXC
HS0-1135RH/SAMPLE	5962F9676701VPC	HS9-OP470ARH-Q	5962R9853301VXC
HS0-1135RH-Q	5962F9676701V9A	HS9-OP470ARH-QS9000	5962R9853301VXC
HS0-1145RH-Q	5962F9683001V9A	HS-OP470ARHEV1Z	N/A
HS0-5104AEH-Q	5962R9569002V9A	HSYE-117-8	5962-9954703QYC
HS0-5104ARH/SAMPLE	N/A	ISL70218SEHF/PROTO	N/A
HS0-5104ARH-Q	5962R9569001V9A	ISL70218SEHMF	N/A
HS0-OP470AEH-Q	5962R9853302V9A	ISL70218SEHVF	5962R1222201VXC
HS0-OP470ARH/SAMPLE	N/A	ISL70218SEHVX	5962R1222201V9A
HS0-OP470ARH-Q	5962R9853301V9A	ISL70218SRHF/PROTO	N/A
HS1-5104AEH-Q	5962R9569002VCC	ISL70218SRHMEVAL1Z	N/A
HS1-5104ARH/PROTO	N/A	ISL70218SRHMF	N/A
HS1-5104ARH-8	5962R9569001QCC	ISL70218SRHMX	N/A
HS1-5104ARH-Q	5962R9569001VCC	ISL70218SRHX/SAMPLE	N/A
HS1-5104ARH-T	5962R9569001TCC	ISL70227MHEVAL1Z	N/A
HS1B-0546RH/PROTO	N/A	ISL70227SEHF/PROTO	N/A
HS1B-0546RH-Q	5962D9569301VXC	ISL70227SEHMF	N/A
HS1B-0547RH/PROTO	N/A	ISL70227SEHVF	5962R1222301VXC
HS1B-0547RH-Q	5962D9569302VXC	ISL70227SEHVX	5962R1222301V9A
HS1B-0547RH-QS9000	5962D9569302VXC	ISL70227SRHF/PROTO	N/A
HS1B-0548RH/PROTO	N/A	ISL70227SRHMF	N/A
HS1B-0548RH-Q	5962D9569401VEC	ISL70227SRHMX	N/A
HS1B-2420RH/PROTO	N/A	ISL70227SRHX/SAMPLE	N/A
HS1B-2420RH-Q	5962R9566901VCC	ISL70417SEHEVAL1Z	N/A
HS1B-2420RH-QS2732	5962R9566901VCC	ISL70417SEHF/PROTO	N/A
HS1B-2420RH-QS9000	5962R9566901VCC	ISL70417SEHVF	5962F1222801VXC
HS7B-1100RH/PROTO	N/A	ISL70417SEHVX	5962F1222801V9A
HS7B-1100RH-Q	5962F9467602VPC	ISL70417SEHX/SAMPLE	N/A
HS7B-1115RH-Q	5962F9678501VPC	ISL71090SEH12EV1Z	N/A
HS7B-1135RH/PROTO	N/A	ISL71090SEH25EV1Z	N/A
HS7B-1135RH-Q	5962F9676701VPC	ISL71090SEHF12/PROTO	N/A
HS7B-1135RH-QS2732	5962F9676701VPC	ISL71090SEHF25/PROTO	N/A
HS7B-1145RH/PROTO	N/A	ISL71090SEHF50/PROTO	N/A
HS7B-1145RH-Q	5962F9683001VPC	ISL71090SEHF75/PROTO	N/A
HS9-1135RH/PROTO	N/A	ISL71090SEHVF12	5962R1321101VXC
HS9-1135RH-Q	5962F9676701VXC	ISL71090SEHVF25	5962R1321102VXC
HS9-5104AEH-Q	5962R9569002VXC	ISL71090SEHVF50	5962R1321103VXC
HS9-5104ARH/PROTO	N/A	ISL71090SEHVF75	5962R1321104VXC
HS9-5104ARH-8	5962R9569001QXC	ISL71090SEHVX12	5962R1321101V9A
HS9-5104ARH-Q	5962R9569001VXC	ISL71090SEHVX25	5962R1321102V9A
HS9-5104ARH-QS9000	5962R9569001VXC	ISL71090SEHVX50	5962R1321103V9A

Products Affected – cont.

Intersil Part Number	DLA SMD Part Number
ISL71090SEHVX75	5962R1321104V9A
ISL71090SEHX12SAMPLE	N/A
ISL71090SEHX25SAMPLE	N/A
ISL71090SEHX50SAMPLE	N/A
ISL71090SEHX75SAMPLE	N/A
ISL72991QF	5962-0250301QXC
ISL73096EHVF	5962F0721804VXC
ISL73096RHF/PROTO	N/A
ISL73096RHVF	5962F0721801VXC
ISL73096RHFVS2732	5962F0721801VXC
ISL73096RHVX	5962F0721801V9A
ISL73096RHX/SAMPLE	N/A
ISL73127RHF/PROTO	N/A
ISL73127RHVF	5962F0721802VXC
ISL73127RHFVS2732	5962F0721802VXC
ISL73127RHFVS9000	5962F0721802VXC
ISL73127RHVX	5962F0721802V9A
ISL73127RHX/SAMPLE	N/A
ISL73128RHF/PROTO	N/A
ISL73128RHVF	5962F0721803VXC
ISL73128RHFVS2732	5962F0721803VXC
ISL73128RHVX	5962F0721803V9A
ISL73128RHX/SAMPLE	N/A
ISL7457SEHVF	5962D0823002VXC
ISL7457SRHF/PROTO	N/A
ISL7457SRHQF	5962D0823001QXC
ISL7457SRHQFS9003	5962D0823001QXC
ISL7457SRHVF	5962D0823001VXC
ISL7457SRHFVS9000	5962D0823001VXC
ISL7457SRHVX	5962D0823001V9A
ISL7457SRHX/SAMPLE	N/A
MD82C52/7	5962-9581701VXC
MD82C59A/7	5962-9571801VXC