

RENESAS TOOL NEWS on April 1, 2014: 140401/tn4

Applilet3 for 78K Revised

We have revised the Applilet3 for 78K from V1.00.00 to V1.01.00.

1. Description of Revision

The following problem in CubeSuite+, which was announced by Renesas Tool News Document No. 131016/tn1, is shared by the Applilet3 for 78K V1.00.00. The problem has now been fixed in V1.01.00.

- With code for initialization when setting external interrupts (78K0R/Kx3-L)

For details of the problem, go to:

https://www.renesas.com/search/keyword-search.html#genre=document&q=131016tn1_e

2. Updating Your Product

Download the installer of the product from the following URL:

https://www.renesas.com/applilet_download

The installer will be published on this site on April 7.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.