AINT							
	Integrated Device Technology, Inc. 2975 Stender Way, Santa Clara, CA - 95054	90					
Phone #: (408) 727-6116 Fax #: (408) 727-2328 Errata Notification							
EN #: LEN-02-02	Errata Revision #: 0						
Issue Date: April 29, 2002	Effective Date: April 29, 2002						
Product Affected: IDT74CBTL	V3862						
ERRATA DETAILS:	ATTACHMENT	Yes 🗌 No					
Data Sheet Errata							
Device Errata Device Manual Errata		Characterization data on IDT74CBTLV3862 OE vs. OE disable times					
Application Notes Errata	requires two sets of specifications be shown (Please see the attachment for the detail).	In data sheet.					
Other (Please Specify)	(r lease see the attachment for the detail).						
IDT Web Site Location:							
http://www.idt.com/products/pages/	Bus_Switches.html						
CUSTOMER NOTIFICATION:							
	DT has decided to notify you through this Errata Notifica notification in details prior to the use of affected product						
	w or E-Mail to request additional information.	• • • •					
If you have any questions, plea	ase feel free to contact your local IDT distributor o	or sales representative.					
Customer:	E-Mail Address:						
Name/Date:	Phone #:						
Title:	Fax # :						
CUSTOMER COMMENTS:							
	~						
IDT FRA-0048-01 (Rev. 01)	07/26/01 Page 1	Refer to: QCA-1795					



Integrated Device Technology, Inc. 2975 Stender Way, Santa Clara, CA - 95054 Phone #: (408) 727-6116 Fax #: (408) 727-2328

Attachment for Errata # LEN-02-02

Switching Characteristics

OLD TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V + - 0.3V	
		Min	Max	Min	Max
Tdis	Output Disable Time \overline{OE} or OE to A or B	1ns	5ns	1ns	5ns

NEW TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V + -0.3V	
	i arameter	Min	Max	Min	Max
Tdis	Output Disable Time \overline{OE} to Aor B	1ns	5ns	1ns	5ns
Tdis	Output Disable Time OE to Aor B	1ns	5ns	1ns	бns