

# RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan  
 Renesas Electronics Corporation

Product Category	MPU/MCU	Document No.	TN-SH7-A768A/E	Rev.	1.00
Title	Error correction about External Wait Timing Example of Bus state controller		Information Category	Technical Notification	
Applicable Product	SH7205 Group SH7265 Group	Lot No.	Reference Document	SH7205 Group Hardware Manual (REJ09B0372-0200) SH7265 Group Hardware Manual (REJ09B0351-0200)	
		ALL			

We would like to inform you of the following error correction about Bus state controller (BSC) in the above-mentioned applicable products.

Error correction

[Error]




Figure 10.7 External Wait Timing Example (Page Read Access to 16-Bit Channel)

[Correction]




Figure 10.7 External Wait Timing Example (Page Read Access to 16-Bit Channel)