

## Note on Using e2 studio, Eclipse open-source based Integrated Development Environment, V3.0.0.22, V3.0.1.07, and V3.0.1.08

When using the e2 studio integrated development environment (IDE) V3.0.0.22, V3.0.1.07 and V3.0.1.08, take note of the following problem:

- When debugging with e2 studio

---

### 1. Product Concerned

- e2 studio V3.0.0.22, V3.0.1.07 or V3.0.1.08

### 2. MCUs Involved

All MCUs except for the RX64M group

### 3. Description

When starting the e2 studio debugger with the "Renesas Coverage" view open, the e2 studio may fail to response in some cases.

This problem can occur regardless of the emulator and simulator used.

### 4. Workaround

Should you see the problem, please take the following steps:

- (1) Close the e2 studio with the close button at the upper-right corner.
- (2) Restart the e2 studio, and before connecting to the debugger, close the "Renesas Coverage" view on Debug Perspective.
- (3) Restart the e2 studio, then connect the debugger.

### 5. Schedule for Fixing the Problem

This problem has been fixed in V3.0.1.09 version of the e2 studio. For details of V3.0.1.09, see RENESAS TOOL NEWS Doc No. 140708/tn2.

The details can also be referenced from the following URL:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140708tn2>

This page will be published on July 9, 2014.

---

**[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.