

RENESAS TOOL NEWS on January 16, 2004: RSO-HEW_2-040116D

A Note on Using Integrated Development Environment High-performance Embedded Workshop --On Editor Window--

Please take note of the following problem in using the High-performance Embedded Workshop:

- On displaying files edited by an external editor on the Editor window
-

1. Products and Versions Concerned

- (1) High-performance Embedded Workshop Version 3.0.02 (release 5) bundled with the M3T-CC32R V.4.20 Release 1 cross-tool kit
- (2) High-performance Embedded Workshop Version 3.0.02 (release 5) updated by the hewv3002u2.exe updater.

2. Description

If a file opened in the Editor window is edited by an external editor and then saved in the window, the window will not reflect the edited results. Note, however, that the edited results are saved in the file though they will not be displayed in the Edited window.

3. Workaround

After editing the file by an external editor and saving it in the Editor window, close the file once and then reopen it, which displays the updated file.

4. Schedule of Fixing the Problem

This problem has already been fixed in the High-performance Embedded Workshop V.3.0.05.

In the High-performance Embedded Workshop V.3.0.05, it confirms that you want it to

read the edited file by message, and if you click OK, it updates the display in the Editor window.

For the description of the revision in the High-performance Embedded Workshop V.3.0.05, see RENESAS TOOL NEWS (RSO-HEW_1-040116D) "Integrated Development Environment High-performance Embedded Workshop Updated to Ver.3.0.05" issued on January 16, 2004, in this series of news.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.