

RENESAS TOOL NEWS on October 16, 2003: RSO-TM-031016D

A Note on Using Integrated Development Environment TM

Please take note of the following problem in using the TM, an integrated development environment:

- On editing commands using the project editor
-

1. Versions Concerned

TM V.3.20 -- V.3.20A

2. Description

If a command is edited in the following steps, a link error that does not appear before editing may arise because the contents of the command file are not updated correctly (if a rebuild is executed, the TM works properly):

- (1) The project editor is displayed.
- (2) The <Project name>.cmd file is opened in the project tree and then the "Project" -> "Edit item" -> "Command" menu is selected.
- (3) A command that includes no redirection character (> or >>) is placed in the first line of the command file in the Command dialog box.

3. Workaround

Be sure to place a command that includes a redirection character (> or >>) in the first line of the command file.

4. Schedule of Fixing the Problem

We plan to fix this problem in our next release of the product.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.