R20TS0456EJ0100

Rev.1.00

Jul. 16, 2019

[Upgrade to revision]

CS+ Code Generator for RL78 (CS+ for CC),

CS+ Code Generator for RL78 (CS+ for CA,CX),

e² studio Code Generator Plug-in,

AP4 Coding Assistance Tool for RL78,

Applilet3 Coding Assistance Tool for RL78

Outline

We have updated the products in the title as follows.

- (1) CS+ Code Generator for RL78 (CS+ for CC): V2.17.00 to V2.18.00
- (2) CS+ Code Generator for RL78 (CS+ for CA,CX): V2.17.00 to V2.18.00
- (3) e² studio Code Generator Plug-in: V2.13.0 to V2.14.0
- (4) AP4 for RL78: V1.16.00 to V1.17.00
- (5) Applilet3 for RL78: V1.16.00 to V1.17.00


Products and Versions to Be Updated

- CS+ Code Generator for RL78 (CS+ for CC) V2.17.00 and earlier versions
- CS+ Code Generator for RL78 (CS+ for CA,CX) V2.17.00 and earlier versions
- e² studio V7.2.0 (Code Generator plug-in V2.13.0) and earlier versions
- AP4 for RL78 V1.16.00 and earlier versions
- Applilet3 for RL78 V1.16.00 and earlier versions

Description of the Update

The main feature of the update is described in section 2.1. For details, refer to the following release notes.

- CS+ Code Generators for RL78 (CS+ for CC) and CS+ Code Generators for RL78 (CS+ for CA,CX) CS+ Code Generator for RL78 (CS+ for CC), (CS+ for CA,CX) V2.18.00 Release Note (Scheduled to be released on July 22.)
 - https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ut4559
- e² studio Code Generator Plug-in
 - e² studio V7.5.0 Release Note (Scheduled to be released on July 22.)
 - https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ut4556
- AP4 for RL78
 - AP4 for RL78 V1.17.00 Release Note (Scheduled to be released on July 22.)
- https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ut4557
- Applilet3 for RL78
 - Applilet3 for RL78 V1.17.00 Release Note (Scheduled to be released on July 22.)
 - https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ut4558





2.1 Issues Fixed

The issues described in the following note have been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0432EJ0100

1. PLL clock setting of clock generator

Applicable devices: RL78/F13, RL78/F14 and RL78/F15 groups

2. RTC operation clock setting of clock generator

Applicable devices: RL78/F13, RL78/F14, RL78/F15 and RL78/D1A groups

For details about these issues, see the URL below.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0432

3. Updating Your Product

The update method varies depending on the product you are using.

See the following for details. The updates are available free of charge.

3.1 Updating CS+ Code Generator for RL78

For updating CS+, refer to "4. Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0442EJ0100. (Scheduled to be released on July 22.)

https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ts0442

3.2 Updating the e² studio Code Generator Plug-in

For updating e² studio, refer to "3. Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0453EJ0100. (Scheduled to be released on July 22.)

https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ts0453

Note that the Code Generator plug-in cannot be updated by itself.

3.3 Updating AP4 and Applilet3 for RL78

To install the program, download the installer from the URL below. (The installer will be available on July 22.)

https://www.renesas.com/applilet_download



Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jul.16.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

 $\hbox{@}$ 2019. Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.0