[Upgrade to revision]

CS+ Device Information for RH850 Family V7.00.01

R20TS0350EJ0100 Rev.1.00 Oct. 01, 2018

Outline

CS+ device information for RH850 family has been updated from V7.00.00 to V7.00.01.

1. Products and Versions to Be Updated

- CS+ Device Information for RH850 V3.00.00 or later
- CubeSuite+ Device Information for RH850 (CubeSuite+ DevInfo_RH850) V1.00.04 or earlier

Check the version number of "CS+ Device Information for RH850" or "CubeSuite+ DevInfo_RH850" by following the steps listed under [Components] from the URL below.

https://www.renesas.com/cs+ ver

2. Items Revised

The main feature of the update is as follows. For details, refer to the following URL:

This information will be available on October 5.

https://www.renesas.com/cs+/eng/CSPlus DevInfo RH850.html

2.1 Addition of Supported Devices

Support for devices in the following group has been added:

- RH850/D1M group (D1M1-V2)
- RH850/E1M-S2 group

2.2 Modification of Device Information

The device information in the following groups has been modified:

- RH850/D1M group (D1M1, D1M1H, D1M1A, D1M2, D1M2H)
- RH850/D1L group

3. Updating Your Product

CS+ device information can be updated online free of charge. Update method varies by the edition of your CS+.

Note: A license for C Compiler Package V1 for RH850 (CC-RH) cannot eliminate the restrictions on the evaluation edition of C Compiler Package V2 for RH850 (CC-RH).

To lift the restrictions and use the Compiler V2 for RH850 (CC-RH), please purchase the professional edition of C Compiler Package V2 for RH850 (CC-RH).

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) Start menu → Programs, select Renesas Electronics CS+ to start the Update Manager. This service will be available on October 5.

Note: If you start CS+ when the rapid start is enabled, exit CS+ and start the Update Manager. When CS+ is contained in the notification area (system tray) in Windows due to rapid start, an error occurs and the following message is output:

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running.

Installation will be resumed next time you start the tool.

(2) Download the software tools from the following URL for installation:

The program will be available on October 5.

https://www.renesas.com/cs+_download

3.2 For CubeSuite+ V2.00.00 ~ 2.02.00

Update your program in the same way as section 3.1.

3.3 For CubeSuite+ V1.03.00 or Earlier

Download and install the evaluation edition of CS+ for CC V7.00.00 from the following URL. After installation, update your program in the same way as section 3.1.

The program will be available on October 5.

https://www.renesas.com/cs+ download

Revision History

| | | Description | |
|------|---------------|-------------|----------------------|
| Rev. | Date | Page | Summary |
| 1.00 | Oct. 01, 2018 | - | First edition issued |
| | | | |

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.1