

[Upgrade to revision]

R20TS0455EJ0100

Rev.1.00

Jul. 16, 2019

e² studio Smart Configurator Plug-in,

Smart Configurator for RX V2.2.0,

CS+ RX Smart Configurator Communication Plugins V1.02.04

Outline

We have updated the products in the title as follows.

- (1) e² studio Smart Configurator Plug-in: V2.1.0 to V2.2.0
- (2) Smart Configurator for RX: V2.1.0 to V2.2.0
- (3) CS+ RX Smart Configurator Communication Plugins: V1.02.03 to V1.02.04

1. Products and Versions to Be Updated

- e² studio V7.3.0 (Smart Configurator Plug-in V2.1.0) and earlier versions
- Smart Configurator for RX V2.1.0 and earlier versions
- CS+ RX Smart Configurator Communication Plugins V1.02.03 and earlier versions

2. Description of the Update

The main features of the update are described in the following sections. For details, refer to the following release notes.

- e² studio Smart Configurator Plug-in
e² studio V7.5.0 Release Note (Scheduled to be released on July 22.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4556>
- Smart Configurator for RX
Smart Configurator for RX V2.2.0 Release Note. (Scheduled to be released on July 22.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4487>

2.1 Addition of Supported Devices

Supported devices have been added for the following group.

- RX72M group

For a list of the supported devices, refer to the URL below:

<https://www.renesas.com/smart-configurator>

2.2 Issues Fixed

The issues described in the following notes have been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0434EJ0100

1. When using self-diagnosis function of 12-bit A/D converter in Single Scan Mode
Applicable devices: RX230 and RX231 groups
2. When using Serial Peripheral Interface clock synchronous mode in slave transmit
Applicable devices: RX66T and RX72T groups
3. When using I²C Bus Interface with Fast-mode Plus enabled
Applicable devices: RX64M, RX651, RX65N, and RX71M groups

For details about these issues, see the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0434>

(2) RENESAS TOOL NEWS, Document No. R20TS0436EJ0100

1. When using general PWM timer
Applicable devices: RX66T and RX72T groups

For details about this issue, see the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0436>

3. Updating Your Product

The update method varies depending on the product you are using.

See the following for details. The updates are available free of charge.

3.1 Updating e² studio Smart Configurator Plug-in

For updating e² studio, refer to "3. Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0453EJ0100. (Scheduled to be released on July 22.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0453>

Note that the Smart Configurator Plug-in cannot be updated by itself.

3.2 Updating Smart Configurator for RX and CS+ RX Smart Configurator Communication Plugins

Download the Smart Configurator for RX (an installer) from the following URL for an installation. If you are using CS+, you will also need to download and install the CS+ plug-in, which is required to use Smart Configurator for RX with CS+.

(The installer will be available on July 22.)

<https://www.renesas.com/smart-configurator#downloads>

Smart Configurator for RX V2.2.0

CS+ RX Smart Configurator Communication Plugins V1.02.04 ^(Note)

Note: Install the plug-in, only if you are using CS+.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.16.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.