

A Note on Using E8a Emulator Software

Please take note of the following problem in using E8a Emulator Software:

- With running the self-check program E8aSCP.exe on Windows Vista(R)
-

1. Products and Versions Concerned

The commercial (CD) products and the full-package editions of the update programs of E8a Emulator Software V.1.00 Release 00 through V.1.03 Release 01 are concerned.

(The debugger-package editions of the update programs are excluded.)

2. Description

When the self-check program for the E8a emulator (E8aSCP.exe) included in the products concerned is invoked on Windows Vista(R), the following error message may be displayed:

"Failed to update the system registry.
Please try using REGEDIT."

3. Workarounds

You can neglect the error message. If you neglect it, you can continue your tasks with no problems.

You can also avoid this problem by using the following way:

- Execute the self-check program on Windows Vista(R) selecting the Run as administrator.

If you do so once, the error message will not be displayed when you invoke the self-check program by double-clicking the icon of it.

4. Schedule of Fixing the Problem

This problem has already been fixed in the "self-check program for the E8a emulator" V.1.00.02. Download this problem-fixed program from:

http://www.renesas.com/e8a_download

This Web site will be opened from November 6.
The above URL is one of our global sites.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.