

---

**[Upgrade to Revision]**  
**CS+ Update Manager**

---

R20TS0940EJ0100  
Rev.1.00  
Apr. 16, 2023**Outline**

CS+ Update Manager has been updated from V2.03.01 to V2.03.02.

**1. Products to Be Updated**

CS+ for CC V3.00.00 or later

CS+ for CA, CX V3.00.00 or later

CS+ Update Manager V2.02.00 or later

**2. Description****2.1 Issue Fixed**

The following issue has been fixed.

- The CS+ Update Manager may crash while installing updates without displaying the Finish page.

Related Tool News: <https://www.renesas.com/document/tnn/notes-cs-update-manager>

**3. Updating the Product**

CS+ Update Manager can be updated online free of charge. The update method varies depending on the version/revision of CS+.

**3.1 CS+ V3.00.00 or Later**

Update in either of the following ways.

- (1) Open the Windows Start menu, select [Renesas Electronics CS+], and then run Update Manager.

(The service is available as of April 20.)

**Note:**

If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then run Update Manager.

If the Rapid Startup function is enabled and CS+ is shown in the Windows notification area, the following error message appears.

---

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

---

- (2) Download and install the desired software tool from the link below.

(Tools are available as of April 20.)

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

### 3.2 CubeSuite+ V2.02.00 or Earlier

Update Manager does not support CubeSuite+ V2.02.00 and earlier.

Download and install CS+ for CC V8.09.00 from the link below, and then update the program as shown in 3.1 above.

(The service is available as of April 20.)

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

**Revision History**

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

**Corporate Headquarters**

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

**Contact Information**

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)

**Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.