
[Upgrade to revision]
CS+ Code Generator for RX,
e² studio Code Generator Plug-in,
AP4 Coding Assistance Tool for RX

R20TS0177EJ0100
Rev.1.00
Jul. 16, 2017

Outline

The products in the title will be revised and their version numbers will be changed as follows.

- (1) CS+ Code Generator for RX: V1.13.00 to V1.14.00
- (2) e² studio Code Generator Plug-in: V2.7.0 to V2.8.0
- (3) AP4 Coding Assistance Tool for RX: V1.12.00 to V1.13.00

1. Products and Versions to Be Updated

- All revisions up to V1.13.00 of CS+ Code Generator for RX
- All revisions up to V5.4.0 of e² studio (V2.7.0 of the Code Generator plug-in)
- All revisions up to V1.12.00 of the AP4 coding assistance tool for RX

2. Items Revised

See 2.1 for the major revision points. For details, refer to the following Release Notes.

- CS+ Code Generator for RX
CS+ Code Generator for RX V1.14.00 Release Note (to be available from July 20)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4082>
- e² studio Code Generator Plug-in
e² studio V6.0.0 Release Note (to be available from early August)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4092>
- AP4 Coding Assistance Tool for RX
AP4 for RX V1.13.00 Release Note (to be available from July 20)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4079>

2.1 Description of Modification

The problem regarding the point below has been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0161EJ0101

3. LCD Initialization Code

Applicable MCUs: RX113 group

For details of the problems, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0161>

2.2 Support for Windows

With the expiration of support for Windows Vista, this version does not support Windows Vista.

3. Updating Your Product

The method of updating depends on the product you are using.

Refer to the following for details. Update of either product is free of charge.

3.1 Updating CS+ Code Generator for RX

For the method of updating CS+, refer to section 3, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0186EJ0100. This document will be released in July 20.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0186>

3.2 Updating the e2 studio Code Generator Plug-in

For the method of updating e² studio, refer to section 3, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0180EJ0100. This document will be released in early August.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0180>

Note that you cannot update only the Code Generator plug-in.

3.3 Updating the AP4 Coding Assistance Tool for RX

Download the installer from the URL below to install the program. This installer will be available from July 20.

https://www.renesas.com/applilet_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul. 16, 2017	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
 Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.