

Product Change Notice (PCN)

Subject: Invalidation of DEMKO and FIMKO certification Publication Date: 6/30/2022 Effective Date: 7/5/2022(Deletion of DEMKO mark), 8/1/2022(Deletion of FIMKO mark)

Revision Description: Initial Release

Description of Change:

- Invalidation of the DEMKO and FIMKO certification
- Invalidation of certification in Data Sheet (DEMKO: Invalid from 1 Jul. 2022, FIMKO: Invalid from 1 Aug. 2022)
- Deletion of the DEMKO and FIMKO certification mark on label

DEMKO certification of the products shipped from the factory earlier than 30 Jun. 2022 is valid. FIMKO certification of the products shipped from the factory earlier than 31 Jul. 2022 is valid.

Products except PS2701-1, PS2701A-1, PS2705-1, PS2705A-1 in affected product list

	Current	Change	
Factory Shipment Date	By 30 Jun. 2022	From 5 Jul. 2022 to 31 Jul. 2022	From 1 Aug. 2022
DEMKO Cert.	Valid	Invalid	Invalid
FIMKO Cert.	Valid	Valid	Invalid
Label on packing	Nº bsi. Image: Constraint of the second sec	Deletion of DEMKO mark St. Image: Constraint of the state o	Deletion of FIMKO mark SN bsi. @@ Discretation DN PS2561DL1YVF3A00118B/R2 Po-Free T. SPN PS2561DL-1Y-V-F3A 002G116LR2 WEAPLING PN PS2561DL-1Y-V-F3 Display PN PS2561DL-1Y-V-F3A 002G116LR2 WEAPLING PN PS2561DL-1Y-V-F3A 0
Label on reel	(2979 N: P528510-1-V-F3 (P)WTP: P528510-1-V-F3A (F)WTP: P528510-1-V-F	CIPIPINE PS2861B-1-V-F3 (PIPINE PS2861B-1-V-F3 (PIPINE PS2861B-1-V-F3 (PIPINE PS2861B-1-V-F3A (SSNOL32	(27/P/N: P526L16:1-V-F3 (PINTP: P525GLD: 1-V-F3 (IPINTS: P525GLD: 1-V-F3-A (IPINTS:
Circled in red above	® _® ®⊗	® _® s	® \$

GET-12380 PC-APW-A003A/E

PS2701-1, PS2701A-1, PS2705-1, PS2705A-1 in affected product list

	Current	Cha	inge
Factory Shipment Date	By 30 Jun. 2022	From 5 Jul. 2022 to 31 Jul. 2022	From 1 Aug. 2022
DEMKO Cert.	Valid	Invalid	Invalid
FIMKO Cert.	Valid	Valid	Invalid
Label on packing	Physic Physic D/N PS2701A1F5A.0118B/R2 Receiver SPN PS2701A-1-F3-A 002G116LL2 Model in Japan PN PS2701A-1-F3 P0110 PD 124446105V-001 2014/01/10 PCD 0000184865 TC 1402 1230A4567 SLOT YL2209K801 Control of the second sec	No change Photosi Photosi D/N PS2701A4F5A0118B/R2 SPN PS2701A4F5A0118B/R2 SPN PS2701A4-F3A 002G116LL2 Microsoft Pro- Microsoft Pro- Microsoft Pro- Microsoft Pro- Microsoft Pro- Microsoft Pro- Microsoft Pro- PCD 0000184865 TrC 1402 1230A4567 S.LOT YL2209K801 2014/01/10 Sector Pro- Microsoft Pro- Notation P	No change No change Po-Free T. Dr. PSZ701A-1F3A-002G116LL2 Bitter in Japan PN PSZ701A-1-F3
Label on reel	(2P)P/N: P52701A-1-F3 (P)INTP-P52701A-1-F3-A (P)INTP-P52701A-1-F3-A (P)INTS-P52701A-1-F3-A (P)INTS-P52701A-1-F3-A (P)INTS-P52701A-1-F3-A (P)INTP-P52701A-1-F3-A	No change (2P)P/N: P52701A-1-F3 PINTP: P52701A-1-F3-A (FP)NTS: P52701A-1-F3-A (S)SOUCLIZ (S)SOUCLIZ2(S)SOU (T)LOT: 123WB4567	No change (2P)PIN: P52701A-1-F3 (P)INTP: P52701A-1-F3-A (1P)INTP: P52701A-1-F3-A (1P)INTP: P52701A-1-F3-A (1P)INT9: P5270A-1-F3-A (1P)INT9: P5270A-1-F3-A (1P)INT9: P52

Affected Product List:

PS2533-1, PS2533L-1 PS2561-1, PS2561L-1, PS2561L1-1, PS2561L2-1 PS2561A-1, PS2561AL-1, PS2561AL1-1, PS2561AL2-1 PS2561B-1, PS2561BL-1, PS2561BL1-1, PS2561BL2-1 PS2561D-1, PS2561DL-1, PS2561DL-1, PS2561DL2-1 PS2562-1, PS2562L-1, PS2562L1-1, PS2562L2-1 PS2565-1, PS2565L-1, PS2565L1-1, PS2565L2-1 PS2581L1, PS2581L2 PS2581AL1, PS2581AL2 PS2701-1, PS2701A-1 PS2705-1, PS2705A-1 PS2761B-1 PS2861B-1	PS8501, PS8501L1, PS8501L2, PS8501L3 PS8502, PS8502L1, PS8502L2, PS8502L3 PS8551L4 PS9513, PS9513L1, PS9513L2, PS9513L3 PS9587, PS9587L1, PS9587L2, PS9587L3
--	--

Reason for Change:

Because DEMKO and FIMKO certifications become invalid.

Impact on Fit, Form, Function, Quality & Reliability: None

Product Identification:

It is possible to distinguish by the Lot Number. Please contact your Renesas sales representative.

Qualification Status: N/A Sample Availability Date: N/A Device Material Declaration: N/A

For additional information regarding this notice, please contact your Renesas sales representative.