

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RZ*-A013A/E	Rev.	1.00
Title	Correction for Incorrect description notice of Module Stop Control Register B in RZ/T1 Group User's Manual Hardware.		Information Category	Technical Notification		
Applicable Product	RZ/T1 Group	Lot No.	Reference Document	RZ/T1 Group User's Manual Hardware Rev1.1 R01UH0483EJ0110 Rev.1.10		
		All lots				

Incorrect description of Module Stop Control Register B (MSTPCRB) in the RZ/T1 Group User's Manual Hardware Rev1.1. have been found. This document describes corrections for the incorrect description.

## 1. Detail of a correction

Page	Objects	Before correction	After correction
257	9.2.2 Module Stop Control Register (MSTPCRB) bit18	MSTPCRB18 *1	MSTPCRB18 <del>*1</del>
258		Note 3. This bit is reserved for products other than those incorporating an R-IN Engine. It is read as 1. The write value should always be 1.	Note 3. This bit shows Ethernet MAC/HW-RTOS Module Stop for products incorporating an R-IN Engine. This bit shows Ethernet MAC Module Stop for products other than those incorporating an R-IN Engine.