
[Upgrade to Revision]

R20TS0839EJ0100

Rev.1.00

CS+ Device Information for RL78 V8.07.01

Apr. 16, 2022

Outline

CS+ Device Information for RL78 has been updated from V8.07.00 to V8.07.01.

1. Item to Be Updated

- CS+ for CC Device Information for RL78 V3.00.00 or later

To check the version of "CS+ for CC Device Information for RL78", follow the instructions under [Components] at the URL below.

<https://www.renesas.com/software-tool/csplus-version>

2. Description

The main changes are as follows. Refer to the link below for details.

(Information will be uploaded on April 20.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RL78.html

2.1 Correction of Device Information

The device information of the following group has been corrected.

- RL78/F24 group
R7F124FBJ3xNP, R7F124FBJ4xNP, R7F124FBJ5xNP,
R7F124FGJ3xFB, R7F124FGJ4xFB, R7F124FGJ5xFB,
R7F124FLJ3xFB, R7F124FLJ4xFB, R7F124FLJ5xFB,
R7F124FMJ3xFB, R7F124FMJ4xFB, R7F124FMJ5xFB,
R7F124FPJ3xFB, R7F124FPJ4xFB, R7F124FPJ5xFB

3. Updating the Product

3.1 CS+ V3.00.00 or Later

Update in either of the following ways.

- (1) On the Start menu, select Programs, Renesas Electronics CS+, and then run Update Manager.

(The Update Manager will be available from April 20.)

Note:

Firstly, check if CS+ has been started with the Rapid Startup function enabled. If it has, close and restart CS+, and then run the Update Manager.

If the CS+ icon is shown in the Windows notification area due to the Rapid Startup function, the following error message appears:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download the desired software tool from the link below and install it.

(The tools will be available from April 20.)

<https://www.renesas.com/software-tool/cs#download>

3.2 CubeSuite+ V2.00.00 to V2.02.00

Refer to 3.1 and update in the same way.

3.3 CubeSuite+ V1.03.00 or Earlier

The Update Manager is not supported. Download CS+ for CC V8.07.00 from the link below, install it, and then update the program in the same way as 3.1.

<https://www.renesas.com/software-tool/cs#download>

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.22	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/