

Supplemental Information

This Document Errata reflects changes required for the device datasheet of 82V3380A.

Revision History

March 28, 2011: First version of documentation errata for the affected devices.

Errata Item

Pages 43, Table 28 “Outputs on OUT3 & OUT7 if Derived from T4 APLL”
- Add a Note at the bottom of the table

CURRENT:

No comment regarding errata.

CHANGE TO:

Add Note 4:

OUT7 doesn't support 25MHz or 125MHz when Non-Ethernet clock signals are selected for OUT3.