

Supplemental Information

This Document Errata reflects corrections made on the datasheet for device 8534-01.

Revision History

May 9, 2008: First version of documentation errata for this device. There is no change to the original characteristics or design of the device. This is only a change to the datasheet to correct a datasheet error published December 6, 2007 – May 8, 2008. Datasheet revisions published prior to December 6, 2007, were correct.

Errata Item

Pin Assignment

Page	Description of Change
1	Rotated pin orientation 90 degrees back to the correct orientation. Original datasheet published September 14, 2004 – December 5, 2007 showed the correct pin orientation.

From: Pin Assignment published in December 6, 2007 – May 8, 2008 datasheet

To: Correct Pin Assignment

