

List of EOL Products Supported for Repair ^(*1)

| Product name | Repair period ^(*2) |
|------------------|--------------------------------|
| ROE417250MCU00 | Until the end of May 2022 |
| QB-70F3539-PD | Until the end of November 2022 |
| ROE000010KCE00 | Until the end of December 2022 |
| QB-70F3537-PD | Until the end of May 2023 |
| M32100T5-SDI-E | Until the end of November 2023 |
| QB-78F1026-ZZZ | Until the end of November 2023 |
| QB-78K0DX2-ZZZ | Until the end of November 2023 |
| QB-78K0FX2L-ZZZ | Until the end of November 2023 |
| QB-78K0FX2-ZZZ | Until the end of November 2023 |
| QB-78K0IX2-ZZZ | Until the end of November 2023 |
| QB-78K0KX2C-ZZZ | Until the end of November 2023 |
| QB-78K0KX2L-ZZZ | Until the end of November 2023 |
| QB-78K0KX2-ZZZ | Until the end of November 2023 |
| QB-78K0LX3-ZZZ | Until the end of November 2023 |
| QB-78K0RFX3-ZZZ | Until the end of November 2023 |
| QB-78K0RIX3-ZZZ | Until the end of November 2023 |
| QB-78K0RKX3-ZZZ | Until the end of November 2023 |
| QB-78K0RLX3-ZZZ | Until the end of November 2023 |
| QB-78K0SKX1-ZZZ | Until the end of November 2023 |
| QB-V850E2-EE | Until the end of November 2023 |
| QB-V850E2FX4H-PD | Until the end of November 2024 |
| QB-V850E2SX4H-PD | Until the end of November 2024 |

(*1) This table lists the product names of the MCU development tools supported for repair after discontinuation.

(*2) For repair reception period, refer to "How to Request Inspection and Repair for Tools" from the URL below.

<https://www.renesas.com/products/software-tools/repair-information.html>

The set items are not listed in this list, but if the products included in the set item are the products to be repaired and are within the repair period, the repair can be accepted.