

PCN#: [IMO-AB-23-0026-1]

Product Change Notice (PCN)

Subject: Notice of Change to Lead Frame for H8S/25xx Products

Publication Date: 3/23/2023

Effective Date: 8/31/2023

Revision History: Initial release

Description of Change:

The lead frame will be changed for H8S/25xx package code PRQP0144KB-A(FP-144J/FP-144JV) products.

• The shape of the inner lead will be altered. There will be no change in the external dimensions of the products.

	Before Change	After Change
Lead frame material	Alloy 42	Cu
Package code	PRQP0144KB-A	PRQP0144KA-A
	(FP-144J/FP-144JV)	(FP-144G/FP-144GV)

Affected Product List:

DF2505FC26DV	DF2506RFC26DV	DF2552FCFTDV
DF2505FC26DV#Z1	DF2551FC26DV	DF2552RFC26DV
DF2506FC26DV	DF2552FC26DV	DF2556FC20DV

Reason for Change:

Due to the end of supply by the lead frame manufacturer.

Impact on Fit, Form, Function, Quality & Reliability:

The form of the affected products will remain unchanged.

There will be no impact on fit, function, quality, and reliability.

Product Identification:

Our production history data can be queried by using the trace code of the product.

Qualification Status: Reliability data can be provided from May 19, 2023.

Sample Availability Date: 6/30/2023

Device Material Declaration: Please contact our sales representatives or distributors.



PCN#: [IMO-AB-23-0026-1]

Note:

1. Acknowledgement must be received by Renesas within 30 days or Renesas will consider the change as approved.

- 2. If timely acknowledgement is provided by Customer, then Customer shall have 90 days from the date of receipt of this PCN to make any objections to this PCN. If Customer fails to make objections to this PCN within 90 days of the receipt of the PCN then Renesas will consider the PCN changes as approved.
- 3. If customer cannot accept the PCN then customer must provide Renesas with a last time buy demand and purchase order.

For additional information regarding this notice, please contact your Renesas sales representative.