

Integrated Device Technology, Inc. 2975 Stender Way, Santa Clara, CA - 95054

Phone #: (408) 727-6116 Fax #: (408) 727-2328

Errata Notification

EN#: IEN02	2-22	Errata Revision #:	10/16/2002		
Issue Date:	October 31, 2002	Effective Date:	October 16, 20	002	
Product Affected: IDT79RC32V334, IDT79RC32V333, and IDT79RC32V332					
ERRATA DETAILS:		AT	ГАСНМЕПТ	☐ Yes	X No
☐ Data Sheet Errata					
□ Device Errata					
Device Manual Errata					
Application Notes Errata					
Other (Please Specify)					
Added items #20 and 21. Added reference to new product RC32333. Changed document name to RC3233x					
to include RC32334, RC32333, and RC32332 devices.					
IDT Web Site Location:					
http://www.idt.com/products/pages/Integrated_Processors-79RC32334.html					
CUSTOMER NOTIFICATION: As a result of Errote listed shows IDT has decided to notify you through this Errote Notification					
As a result of Errata listed above, IDT has decided to notify you through this Errata Notification. We recommend you to review this notification in details prior to the use of affected product in your application.					
Please use acknowledgement below or E-Mail to request additional information.					
If you have any questions, please feel free to contact your local IDT distributor or sales representative.					
Customer:		E-M	Iail Address:		
Name/Date:			Phone #:		
Title:			Fax #:		
CUSTOMER COMMENTS:					