



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

| | |
|--|---|
| PCN #: TB-0609-03 DATE: 06-Oct-2006 Product Affected: All square PQFP and TQFP, MLP Dual, QFP-N, VFQFP-N packages shipped in Tape and Reel Date Effective: 06-Nov-2006 | MEANS OF DISTINGUISHING CHANGED DEVICES: <input type="checkbox"/> Product Mark <input type="checkbox"/> Back Mark <input type="checkbox"/> Date Code <input checked="" type="checkbox"/> Other Starting 06-Nov-2006 |
|--|---|

| | |
|---|---|
| Contact: Geoffrey Cortes Title: Product Quality Phone #: (408) 284-8321 Fax #: (408) 284-1450 E-mail: Geoffrey.Cortes@idt.com | Attachment:: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No See attachment for orientation details. Samples: N/A |
|---|---|

DESCRIPTION AND PURPOSE OF CHANGE:

| | |
|---|---|
| <input type="checkbox"/> Die Technology <input type="checkbox"/> Wafer Fabrication Process <input checked="" type="checkbox"/> Assembly Process <input type="checkbox"/> Equipment <input type="checkbox"/> Material <input type="checkbox"/> Testing <input type="checkbox"/> Manufacturing Site <input type="checkbox"/> Data Sheet <input checked="" type="checkbox"/> Other - Packaging | Pin 1 orientation of all square PQFP and TQFP, MLP Dual, QFP-N and VFQFP-N packages shipped in Tape and Reel packaging will be changed to comply with current EIA Standard (EIA-481-C) requirement. Additional label will be placed on the intermediate box (pizza box) to alert customer of this change. Please see attachment for details. |
|---|---|

RELIABILITY/QUALIFICATION SUMMARY:

There is no change to the product reliability

CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice it will be assumed that this change is acceptable.

IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

| | |
|------------------|---|
| Customer: _____ | <input type="checkbox"/> <i>Approval for shipments prior to effective date.</i> |
| Name/Date: _____ | E-Mail Address: _____ |
| Title: _____ | Phone# /Fax# : _____ |

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGMENT OF RECEIPT:

RECD. BY: _____ DATE: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN #: TB-0609-03

PCN Type: To comply to current EIA Standard (EIA-481-C) requirement.

Data Sheet Change: No

Detail of Change: This change will be implemented on all square PQFP and TQFP, MLP Dual, QFP-N, VFQFP-N packages.

Affected Packages:

| Package Family | IDT Package Nomenclature | Package Description |
|----------------|--------------------------|---------------------|
| PQFP (Square) | DB44, DBG44 | PQFP 44, 10X10MM |
| | DN52, DNG52 | PQFP 52, 14X14MM |
| | PM64, PMG64 | PQFP 64, 14X14MM |
| | PM80, PMG80 | PQFP 80, 14X14MM |
| | PM144, PMG144 | PQFP 144, 28X28MM |
| TQFP (Square) | DE64, DEG64 | TQFP 64, 10X10MM |
| | DK64, DKG64 | TQFP 64, 10X10MM |
| | DQ100, DQG100 | TQFP 100, 14X14MM |
| | DT80, DTG80 | TQFP 80, 12X12MM |
| | DX48, DXG48 | TQFP 48, 7X7MM |
| | EP52, EPG52 | TQFP 52, 10X10MM |
| | ED64, EDG64 | TQFP 64, 10X10MM |
| | ER48, ERG48 | TQFP 48, 7X7MM |
| | PN64, PNG64 | TQFP 64, 14X14MM |
| | PN80, PNG80 | TQFP 80, 14X14MM |
| | PN100, PNG100 | TQFP 100, 14X14MM |
| | PN120, PNG120 | TQFP 120, 14X14MM |
| | PP44, PPG44 | TQFP 44, 10X10MM |
| | PP52, PPG52 | TQFP 52, 10X10MM |
| | PP64, PPG64 | TQFP 64, 10X10MM |
| | PR32, PRG32 | TQFP 32, 7X7MM |
| PR48, PRG48 | TQFP 48, 7X7MM | |
| MLP Dual | NB8, NBG8 | QFP-N 8, 2X2MM |
| QFP-N | ND16, NDG16 | QFP-N 16, 2.5X2.5MM |
| VFQFP-N | NL8, NLG8 | VFQFP-N 8, 3X3MM |
| | NL16, NLG16 | VFQFP-N 16, 3X3MM |
| | NL20, NLG20 | VFQFP-N 20, 4X4MM |
| | NL28, NLG28 | VFQFP-N 28, 6X6MM |
| | NL32, NLG32 | VFQFP-N 32, 5X5MM |
| | NL40, NLG40 | VFQFP-N 40, 6X6MM |
| | NL52, NLG52 | VFQFP-N 52, 8X8MM |
| | NL56, NLG56 | VFQFP-N 56, 8X8MM |
| | NL64, NLG64 | VFQFP-N 64, 9X9MM |
| | NL68, NLG68 | VFQFP-N 68, 10X10MM |
| NL72, NLG72 | VFQFP-N 72, 10X10MM | |




Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138


PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN #: TB-0609-03

FROM:




TO:



Conversion Schedule:

Additional label as shown below will be placed on the intermediate box (pizza box) to alert customer of this change. Label will be placed starting 06-Nov-2006 until 06-Nov-2007. However, please take note that IDT will continue to ship products in existing loading orientation until the inventory has been depleted. Customer may receive shipments in existing or new loading orientation.



● Pin One in Quadrant 1



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------------|-------------------|----------------|----------------|
| IDT10201-PN100-ASM | IDT5T940-30NLGI | IDT7005L20PFGI | IDT7006S17PF |
| IDT10206-PN100-ASM | IDT5T940-30NLI | IDT7005L20PFI | IDT7006S17PFI |
| IDT10214-PN100-ASM | IDT5T9820NLGI | IDT7005L25PF | IDT7006S20PF |
| IDT10215-PN100-ASM | IDT5T9820NLI | IDT7005L25PFI | IDT7006S20PFG |
| ICS1892Y-10 | IDT5T9821NLGI | IDT7005L35PF | IDT7006S25PF |
| ICS1892Y-10LF | IDT5T9821NLI | IDT7005L35PFG | IDT7006S25PFG |
| ICS1892Y-14 | IDT5T9890NLGI | IDT7005L35PFGI | IDT7006S35PF |
| ICS1892Y-14LF | IDT5T9890NLI | IDT7005L35PFI | IDT7006S55PF |
| ICS1893BK | IDT5T9891NLGI | IDT7005L55PF | IDT7006S55PFG |
| ICS1893BKI | IDT5T9891NLI | IDT7005L55PFG | IDT7006S55PFI |
| ICS1893BKILF | IDT5T9950APFGI | IDT7005L55PFI | IDT7007L15PF |
| ICS1893BKLF | IDT5T9950APFI | IDT7005S15PF | IDT7007L15PFG |
| ICS1893BY-10 | IDT5T9950PFGI | IDT7005S15PFI | IDT7007L20PF |
| ICS1893BYI-10 | IDT5T9950PFI | IDT7005S17PF | IDT7007L20PFGI |
| ICS1893Y-10 | IDT5T995APFI | IDT7005S17PFI | IDT7007L20PFI |
| ICS1893YI-10 | IDT5T995PFI | IDT7005S20PF | IDT7007L25PF |
| IDT5T2010NLGI | IDT5V9351PFGI | IDT7005S20PFI | IDT7007L25PFG |
| IDT5T2010NLI | IDT5V9351PFI | IDT7005S25PF | IDT7007L25PFI |
| IDT5T2110NLGI | IDT5V9352PFGI | IDT7005S25PFG | IDT7007L35PF |
| IDT5T2110NLI | IDT5V9352PFI | IDT7005S25PFI | IDT7007L35PFG |
| IDT5T929-10NLGI | IDT5V952PFI | IDT7005S35PF | IDT7007L35PFGI |
| IDT5T929-10NLI | IDT5V9885-001PFGI | IDT7005S35PFG | IDT7007L55PF |
| IDT5T929-30NLGI | IDT5V9885-003PFGI | IDT7005S35PFGI | IDT7007L55PFI |
| IDT5T929-30NLI | IDT5V9885-003PFI | IDT7005S35PFI | IDT7007S15PF |
| IDT5T9306NLGI | IDT5V9885-006NLGI | IDT7005S55PF | IDT7007S15PFG |
| IDT5T9306NLI | IDT5V9885KNLGI | IDT7005S55PFG | IDT7007S20PF |
| IDT5T9310NLGI | IDT5V9885NLGI | IDT7005S55PFI | IDT7007S20PFI |
| IDT5T9310NLI | IDT5V9885NLI | IDT7006L15PF | IDT7007S25PF |
| IDT5T9316NLGI | IDT5V9885PFGI | IDT7006L15PFG | IDT7007S25PFG |
| IDT5T9316NLI | IDT5V9885PFI | IDT7006L15PFI | IDT7007S25PFI |
| IDT5T93GL061PFGI | IDT5V9888NLGI | IDT7006L17PF | IDT7007S35PF |
| IDT5T93GL061PFI | IDT5V9888PFGI | IDT7006L17PFI | IDT7007S55PF |
| IDT5T93GL06NLGI | IDT5V994PFGI | IDT7006L20PF | IDT7007S55PFI |
| IDT5T93GL06NLI | IDT5V994PFI | IDT7006L20PFGI | IDT7008L15PF |
| IDT5T93GL101PFGI | IDT5V9950PFGI | IDT7006L20PFI | IDT7008L15PFG |
| IDT5T93GL101PFI | IDT5V9950PFI | IDT7006L25PF | IDT7008L20PF |
| IDT5T93GL10NLGI | IDT5V995PFGI | IDT7006L25PFG | IDT7008L20PFGI |
| IDT5T93GL10NLI | IDT5V995PFI | IDT7006L35PF | IDT7008L20PFI |
| IDT5T93GL161PFGI | IDT7005L15PF | IDT7006L35PFI | IDT7008L25PF |
| IDT5T93GL161PFI | IDT7005L15PFG | IDT7006L55PF | IDT7008L25PFG |
| IDT5T93GL16NLGI | IDT7005L15PFI | IDT7006L55PFG | IDT7008L25PFI |
| IDT5T93GL16NLI | IDT7005L17PF | IDT7006L55PFI | IDT7008L35PF |
| IDT5T940-10NLGI | IDT7005L17PFI | IDT7006S15PF | IDT7008L45PF |
| IDT5T940-10NLI | IDT7005L20PF | IDT7006S15PFI | IDT7008L55PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|----------------|----------------|-----------------|
| IDT7008L55PFI | IDT7016S12PF | IDT7024S25PFI | IDT70261L20PF |
| IDT7008S15PF | IDT7016S15PF | IDT7024S35PF | IDT70261L20PFG |
| IDT7008S20PF | IDT7016S20PF | IDT7024S35PFG | IDT70261L20PFGI |
| IDT7008S20PFI | IDT7016S25PF | IDT7024S35PFI | IDT70261L20PFI |
| IDT7008S25PF | IDT7016S35PF | IDT7024S55PF | IDT70261L25PF |
| IDT7008S25PFG | IDT7016S35PFI | IDT7024S55PFG | IDT70261L25PFG |
| IDT7008S25PFI | IDT7017L15PF | IDT7024S55PFGI | IDT70261L25PFI |
| IDT7008S35PF | IDT7017L20PF | IDT7024S55PFI | IDT70261L35PF |
| IDT7008S45PF | IDT7017L20PFI | IDT7025L15PF | IDT70261L35PFI |
| IDT7008S55PF | IDT7018L15PF | IDT7025L15PFG | IDT70261L55PF |
| IDT7008S55PFGI | IDT7018L20PF | IDT7025L15PFI | IDT70261L55PFG |
| IDT7008S55PFI | IDT7018L20PFI | IDT7025L17PF | IDT70261L55PFI |
| IDT7009L15PF | IDT7019L15PF | IDT7025L17PFI | IDT70261S15PF |
| IDT7009L15PFG | IDT7019L20PF | IDT7025L20PF | IDT70261S15PFG |
| IDT7009L20PF | IDT7019L20PFI | IDT7025L20PFG | IDT70261S15PFI |
| IDT7009L20PFGI | IDT7024L15PF | IDT7025L20PFGI | IDT70261S20PF |
| IDT7009L20PFI | IDT7024L15PFG | IDT7025L20PFI | IDT70261S20PFG |
| IDT7014S12PF | IDT7024L15PFGI | IDT7025L25PF | IDT70261S20PFI |
| IDT7014S12PFG | IDT7024L15PFI | IDT7025L25PFG | IDT70261S25PF |
| IDT7014S12PFI | IDT7024L17PF | IDT7025L25PFI | IDT70261S25PFGI |
| IDT7014S15PF | IDT7024L17PFI | IDT7025L35PF | IDT70261S25PFI |
| IDT7014S20PF | IDT7024L20PF | IDT7025L35PFI | IDT70261S35PF |
| IDT7014S20PFI | IDT7024L20PFG | IDT7025L45PF | IDT70261S35PFI |
| IDT7014S25PF | IDT7024L20PFGI | IDT7025L45PFI | IDT70261S55PF |
| IDT7015L12PF | IDT7024L20PFI | IDT7025L55PF | IDT70261S55PFG |
| IDT7015L15PF | IDT7024L25PF | IDT7025L55PFI | IDT70261S55PFI |
| IDT7015L17PF | IDT7024L25PFI | IDT7025S15PF | IDT7027L15PF |
| IDT7015L20PF | IDT7024L35PF | IDT7025S15PFG | IDT7027L15PFG |
| IDT7015L20PFI | IDT7024L35PFG | IDT7025S15PFI | IDT7027L20PF |
| IDT7015L25PF | IDT7024L35PFGI | IDT7025S17PF | IDT7027L20PFG |
| IDT7015L35PF | IDT7024L35PFI | IDT7025S20PF | IDT7027L20PFGI |
| IDT7015S12PF | IDT7024L55PF | IDT7025S20PFI | IDT7027L20PFI |
| IDT7015S15PF | IDT7024L55PFG | IDT7025S25PF | IDT7027L25PF |
| IDT7015S17PF | IDT7024L55PFI | IDT7025S25PFI | IDT7027L25PFI |
| IDT7015S20PF | IDT7024S15PF | IDT7025S35PF | IDT7027L35PF |
| IDT7015S25PF | IDT7024S15PFG | IDT7025S35PFGI | IDT7027L45PF |
| IDT7015S35PF | IDT7024S15PFI | IDT7025S35PFI | IDT7027L55PF |
| IDT7016L12PF | IDT7024S17PF | IDT7025S45PF | IDT7027L55PFI |
| IDT7016L12PFG | IDT7024S17PFI | IDT7025S45PFI | IDT7027S15PF |
| IDT7016L15PF | IDT7024S20PF | IDT7025S55PF | IDT7027S20PF |
| IDT7016L20PF | IDT7024S20PFG | IDT7025S55PFI | IDT7027S20PFI |
| IDT7016L20PFI | IDT7024S20PFI | IDT70261L15PF | IDT7027S25PF |
| IDT7016L25PF | IDT7024S25PF | IDT70261L15PFG | IDT7027S25PFI |
| IDT7016L35PF | IDT7024S25PFG | IDT70261L15PFI | IDT7027S35PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|-----------------|-----------------|-----------------|
| IDT7027S55PF | IDT707288S25PF | IDT709099L12PF | IDT709269L12PF |
| IDT7027S55PFI | IDT70824L20PF | IDT709099L12PFI | IDT709269L12PFG |
| IDT7028L15PF | IDT70824L20PFG | IDT709099L7PF | IDT709269L12PFI |
| IDT7028L15PFI | IDT70824L25PF | IDT709099L9PF | IDT709269L15PF |
| IDT7028L20PF | IDT70824L25PFI | IDT709099L9PFI | IDT709269L15PFI |
| IDT7028L20PFI | IDT70824L35PF | IDT709149ED8PF | IDT709269L9PF |
| IDT7034L15PF | IDT70824S20PF | IDT709149S10PF | IDT709269L9PFG |
| IDT7034L15PFG | IDT70824S25PF | IDT709149S10PFI | IDT709269S12PF |
| IDT7034L20PF | IDT70824S35PF | IDT709149S12PF | IDT709269S12PFI |
| IDT7034L20PFI | IDT70825L20PF | IDT709149S8PF | IDT709269S15PF |
| IDT7034S15PF | IDT70825L20PFI | IDT70914ED12PF | IDT709269S15PFI |
| IDT7034S15PFI | IDT70825L25PF | IDT70914S12PF | IDT709269S9PF |
| IDT7034S20PF | IDT70825L35PF | IDT70914S12PFG | IDT709279L12PF |
| IDT7035L15PF | IDT70825S20PF | IDT70914S15PF | IDT709279L12PFG |
| IDT7035L20PF | IDT70825S25PF | IDT70914S15PFG | IDT709279L12PFI |
| IDT7035L20PFI | IDT70825S25PFI | IDT70914S15PFI | IDT709279L15PF |
| IDT7035S15PF | IDT70825S35PF | IDT70914S20PF | IDT709279L15PFI |
| IDT7035S20PF | IDT709079L12PF | IDT70914S20PFI | IDT709279L9PF |
| IDT7037L15PF | IDT709079L12PFI | IDT70914S25PF | IDT709279L9PFI |
| IDT7037L20PF | IDT709079L15PF | IDT70914S25PFGI | IDT709279S12PF |
| IDT7037L20PFI | IDT709079L7PF | IDT70914S25PFI | IDT709279S12PFI |
| IDT7038L15PF | IDT709079L9PF | IDT709159L6PF | IDT709279S15PF |
| IDT7038L20PF | IDT709079L9PFI | IDT709159L7PF | IDT709279S9PF |
| IDT7038L20PFI | IDT709079S12PF | IDT709159L7PFI | IDT709289L12PF |
| IDT7052L20PF | IDT709079S12PFI | IDT709159L9PF | IDT709289L12PFI |
| IDT7052L25PF | IDT709079S15PF | IDT709159L9PFI | IDT709289L6PF |
| IDT7052L25PFI | IDT709079S15PFI | IDT709169L6PF | IDT709289L7PF |
| IDT7052L35PF | IDT709079S7PF | IDT709169L7PF | IDT709289L9PF |
| IDT7052S20PF | IDT709079S9PF | IDT709169L7PFI | IDT709289L9PFI |
| IDT7052S25PF | IDT709089L12PF | IDT709169L9PF | IDT709349L6PF |
| IDT7052S35PF | IDT709089L12PFI | IDT709169L9PFI | IDT709349L7PF |
| IDT707278L15PF | IDT709089L15PF | IDT709179L12PF | IDT709349L7PFI |
| IDT707278L20PF | IDT709089L15PFI | IDT709179L9PF | IDT709349L9PF |
| IDT707278L20PFI | IDT709089L9PF | IDT709179L9PFI | IDT709349L9PFI |
| IDT707278L25PF | IDT709089S12PF | IDT709189L12PF | IDT709359L6PF |
| IDT707278S15PF | IDT709089S15PF | IDT709189L12PFI | IDT709359L7PF |
| IDT707278S20PF | IDT709089S15PFI | IDT709189L7PF | IDT709359L7PFI |
| IDT707278S25PF | IDT709089S9PF | IDT709189L9PF | IDT709359L9PF |
| IDT707288L15PF | IDT70908L25PF | IDT709189L9PFI | IDT709359L9PFI |
| IDT707288L20PF | IDT70908L30PF | IDT709199L12PF | IDT709369L12PF |
| IDT707288L20PFI | IDT70908L35PF | IDT709199L12PFI | IDT709369L7PF |
| IDT707288L25PF | IDT70908S25PF | IDT709199L7PF | IDT709369L9PF |
| IDT707288S15PF | IDT70908S30PF | IDT709199L9PF | IDT709369L9PFI |
| IDT707288S20PF | IDT70908S35PF | IDT709199L9PFI | IDT709379L12PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|------------------|-----------------|-----------------|
| IDT709379L12PFI | IDT70T9349L12PF | IDT70V06S20PF | IDT70V16S20PF |
| IDT709379L7PF | IDT70T9349L12PFI | IDT70V06S20PFGI | IDT70V16S25PF |
| IDT709379L7PFG | IDT70T9349L7PF | IDT70V06S25PF | IDT70V17L15PF |
| IDT709379L9PF | IDT70T9349L9PF | IDT70V06S25PFI | IDT70V17L20PF |
| IDT709379L9PFI | IDT70T9349L9PFI | IDT70V06S35PF | IDT70V17L20PFI |
| IDT709389L12PF | IDT70T9359L12PF | IDT70V06S45PF | IDT70V18L15PF |
| IDT709389L12PFI | IDT70T9359L12PFI | IDT70V06S55PF | IDT70V18L20PF |
| IDT709389L7PF | IDT70T9359L7PF | IDT70V07L25PF | IDT70V18L20PFI |
| IDT709389L9PF | IDT70T9359L9PF | IDT70V07L25PFG | IDT70V19L15PF |
| IDT709389L9PFI | IDT70T9359L9PFI | IDT70V07L25PFI | IDT70V19L20PF |
| IDT70T05L20PF | IDT70V05L15PF | IDT70V07L35PF | IDT70V19L20PFI |
| IDT70T05L25PF | IDT70V05L15PFG | IDT70V07L35PFGI | IDT70V22L15PF |
| IDT70T05L25PFI | IDT70V05L20PF | IDT70V07L55PF | IDT70V22L20PF |
| IDT70T06L20PF | IDT70V05L20PFGI | IDT70V07S25PF | IDT70V22L20PFG |
| IDT70T06L25PF | IDT70V05L20PFI | IDT70V07S35PF | IDT70V22L20PFI |
| IDT70T06L25PFI | IDT70V05L25PF | IDT70V07S35PFI | IDT70V24L15PF |
| IDT70T15L20PF | IDT70V05L25PFG | IDT70V07S55PF | IDT70V24L15PFG |
| IDT70T15L25PF | IDT70V05L35PF | IDT70V08L15PF | IDT70V24L15PFI |
| IDT70T15L25PFI | IDT70V05L35PFG | IDT70V08L20PF | IDT70V24L20PF |
| IDT70T16L20PF | IDT70V05L35PFI | IDT70V08L20PFGI | IDT70V24L20PFG |
| IDT70T16L25PF | IDT70V05L45PF | IDT70V08L20PFI | IDT70V24L20PFGI |
| IDT70T16L25PFI | IDT70V05L55PF | IDT70V08L25PF | IDT70V24L20PFI |
| IDT70T24L20PF | IDT70V05L55PFG | IDT70V08L35PF | IDT70V24L25PF |
| IDT70T24L25PF | IDT70V05S15PF | IDT70V08L35PFI | IDT70V24L25PFG |
| IDT70T24L25PFI | IDT70V05S15PFG | IDT70V08S15PF | IDT70V24L25PFI |
| IDT70T25L20PF | IDT70V05S20PF | IDT70V08S20PF | IDT70V24L35PF |
| IDT70T25L25PF | IDT70V05S25PF | IDT70V08S20PFI | IDT70V24L35PFG |
| IDT70T25L25PFI | IDT70V05S25PFG | IDT70V08S25PF | IDT70V24L35PFI |
| IDT70T34L20PF | IDT70V05S25PFI | IDT70V08S25PFI | IDT70V24L45PF |
| IDT70T34L25PF | IDT70V05S35PF | IDT70V08S35PF | IDT70V24L55PF |
| IDT70T34L25PFI | IDT70V05S45PF | IDT70V09L15PF | IDT70V24L55PFI |
| IDT70T35L20PF | IDT70V05S55PF | IDT70V09L15PFG | IDT70V24S15PF |
| IDT70T35L25PF | IDT70V05S55PFI | IDT70V09L20PF | IDT70V24S15PFG |
| IDT70T35L25PFI | IDT70V06L15PF | IDT70V09L20PFI | IDT70V24S20PF |
| IDT70T9159L12PF | IDT70V06L15PFG | IDT70V15L15PF | IDT70V24S20PFG |
| IDT70T9159L12PFI | IDT70V06L20PF | IDT70V15L20PF | IDT70V24S20PFI |
| IDT70T9159L7PF | IDT70V06L20PFGI | IDT70V15L25PF | IDT70V24S25PF |
| IDT70T9159L9PF | IDT70V06L20PFI | IDT70V15S15PF | IDT70V24S25PFG |
| IDT70T9159L9PFI | IDT70V06L25PF | IDT70V15S20PF | IDT70V24S25PFI |
| IDT70T9169L12PF | IDT70V06L25PFI | IDT70V15S25PF | IDT70V24S35PF |
| IDT70T9169L12PFI | IDT70V06L35PF | IDT70V16L15PF | IDT70V24S35PFG |
| IDT70T9169L7PF | IDT70V06L45PF | IDT70V16L20PF | IDT70V24S35PFI |
| IDT70T9169L9PF | IDT70V06L55PF | IDT70V16L25PF | IDT70V24S45PF |
| IDT70T9169L9PFI | IDT70V06S15PF | IDT70V16S15PF | IDT70V24S55PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-----------------|-----------------|------------------|
| IDT70V24S55PFG | IDT70V261L45PF | IDT70V27S45PF | IDT70V7278L20PFI |
| IDT70V24S55PFGI | IDT70V261L55PF | IDT70V27S55PF | IDT70V7278L25PF |
| IDT70V24S55PFI | IDT70V261S25PF | IDT70V27S55PFG | IDT70V7278S15PF |
| IDT70V25L15PF | IDT70V261S25PFG | IDT70V27S55PFI | IDT70V7278S20PF |
| IDT70V25L15PFG | IDT70V261S25PFI | IDT70V28L12PF | IDT70V7278S25PF |
| IDT70V25L15PFI | IDT70V261S30PF | IDT70V28L15PF | IDT70V7288L15PF |
| IDT70V25L17PF | IDT70V261S35PF | IDT70V28L15PFG | IDT70V7288L20PF |
| IDT70V25L20PF | IDT70V261S35PFG | IDT70V28L15PFGI | IDT70V7288L20PFI |
| IDT70V25L20PFGI | IDT70V261S35PFI | IDT70V28L15PFI | IDT70V7288L25PF |
| IDT70V25L20PFI | IDT70V261S45PF | IDT70V28L20PF | IDT70V7288L25PFI |
| IDT70V25L25PF | IDT70V261S55PF | IDT70V28L20PFG | IDT70V7288S15PF |
| IDT70V25L25PFG | IDT70V27L15PF | IDT70V28L20PFGI | IDT70V7288S20PF |
| IDT70V25L25PFGI | IDT70V27L15PFG | IDT70V28L20PFI | IDT70V7288S25PF |
| IDT70V25L25PFI | IDT70V27L15PFI | IDT70V28L25PF | IDT70V9079L12PF |
| IDT70V25L30PF | IDT70V27L17PF | IDT70V28L25PFI | IDT70V9079L12PFI |
| IDT70V25L30PFI | IDT70V27L17PFI | IDT70V28VL15PF | IDT70V9079L15PF |
| IDT70V25L35PF | IDT70V27L20PF | IDT70V28VL20PF | IDT70V9079L17PF |
| IDT70V25L35PFG | IDT70V27L20PFG | IDT70V34L15PF | IDT70V9079L6PF |
| IDT70V25L35PFI | IDT70V27L20PFGI | IDT70V34L15PFG | IDT70V9079L6PFG |
| IDT70V25L45PF | IDT70V27L20PFI | IDT70V34L20PF | IDT70V9079L7PF |
| IDT70V25L55PF | IDT70V27L25PF | IDT70V34L20PFI | IDT70V9079L9PF |
| IDT70V25L55PFI | IDT70V27L25PFG | IDT70V34L25PF | IDT70V9079S12PF |
| IDT70V25S15PF | IDT70V27L25PFI | IDT70V34S15PF | IDT70V9079S15PF |
| IDT70V25S17PF | IDT70V27L30PF | IDT70V34S20PF | IDT70V9079S17PF |
| IDT70V25S20PF | IDT70V27L30PFI | IDT70V34S20PFI | IDT70V9079S20PF |
| IDT70V25S20PFG | IDT70V27L35PF | IDT70V34S25PF | IDT70V9079S6PF |
| IDT70V25S25PF | IDT70V27L35PFI | IDT70V35L15PF | IDT70V9079S7PF |
| IDT70V25S25PFG | IDT70V27L45PF | IDT70V35L20PF | IDT70V9079S9PF |
| IDT70V25S25PFGI | IDT70V27L55PF | IDT70V35L20PFI | IDT70V9089L12PF |
| IDT70V25S25PFI | IDT70V27S15PF | IDT70V35L25PF | IDT70V9089L12PFI |
| IDT70V25S30PF | IDT70V27S15PFGI | IDT70V35S15PF | IDT70V9089L15PF |
| IDT70V25S30PFI | IDT70V27S15PFI | IDT70V35S20PF | IDT70V9089L6PF |
| IDT70V25S35PF | IDT70V27S17PF | IDT70V35S25PF | IDT70V9089L7PF |
| IDT70V25S35PFG | IDT70V27S17PFI | IDT70V37L15PF | IDT70V9089L9PF |
| IDT70V25S35PFI | IDT70V27S20PF | IDT70V37L15PFG | IDT70V9089S12PF |
| IDT70V25S45PF | IDT70V27S20PFI | IDT70V37L20PF | IDT70V9089S15PF |
| IDT70V25S55PF | IDT70V27S25PF | IDT70V37L20PFI | IDT70V9089S7PFI |
| IDT70V261L25PF | IDT70V27S25PFG | IDT70V38L12PF | IDT70V9089S9PF |
| IDT70V261L25PFG | IDT70V27S25PFI | IDT70V38L12PFG | IDT70V9089S9PFI |
| IDT70V261L25PFGI | IDT70V27S30PF | IDT70V38L15PF | IDT70V908L25PF |
| IDT70V261L25PFI | IDT70V27S30PFI | IDT70V38L20PF | IDT70V908L30PF |
| IDT70V261L30PF | IDT70V27S35PF | IDT70V38L20PFI | IDT70V908S25PF |
| IDT70V261L35PF | IDT70V27S35PFG | IDT70V7278L15PF | IDT70V908S30PF |
| IDT70V261L35PFI | IDT70V27S35PFI | IDT70V7278L20PF | IDT70V9099L12PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|------------------|------------------|------------------|
| IDT70V9099L12PFI | IDT70V9289L7PF | IDT7130LA55PF | IDT71321SA25TF |
| IDT70V9099L6PF | IDT70V9289L7PFGI | IDT7130LA55PFI | IDT71321SA35PF |
| IDT70V9099L7PF | IDT70V9289L9PF | IDT7130LA55TF | IDT71321SA35TF |
| IDT70V9099L7PFG | IDT70V9289L9PFG | IDT7130LA55TFI | IDT71321SA35TFG |
| IDT70V9099L7PFI | IDT70V9289L9PFI | IDT7130SA100PF | IDT71321SA55PF |
| IDT70V9099L9PF | IDT70V9349L6PF | IDT7130SA20PF | IDT71321SA55PFG |
| IDT70V9099L9PFG | IDT70V9349L7PF | IDT7130SA20PFI | IDT71321SA55PFI |
| IDT70V9099L9PFI | IDT70V9349L7PFI | IDT7130SA20TF | IDT71321SA55TF |
| IDT70V914S12PF | IDT70V9349L9PF | IDT7130SA25PF | IDT71321SA55TFGI |
| IDT70V914S15PF | IDT70V9349L9PFI | IDT7130SA25PFG | IDT71321SA55TFI |
| IDT70V914S20PF | IDT70V9359L12PF | IDT7130SA25TF | IDT7133LA20PF |
| IDT70V914S20PFI | IDT70V9359L6PF | IDT7130SA35PF | IDT7133LA20PFG |
| IDT70V914S25PF | IDT70V9359L6PFG | IDT7130SA35PFI | IDT7133LA25PF |
| IDT70V914S25PFI | IDT70V9359L7PF | IDT7130SA35TF | IDT7133LA25PFG |
| IDT70V9159L6PF | IDT70V9359L7PFI | IDT7130SA55PF | IDT7133LA25PFGI |
| IDT70V9159L7PF | IDT70V9359L9PF | IDT7130SA55PFI | IDT7133LA25PFI |
| IDT70V9159L7PFI | IDT70V9359L9PFI | IDT7130SA55TF | IDT7133LA35PF |
| IDT70V9159L9PF | IDT70V9359S12PF | IDT7130SA55TFI | IDT7133LA35PFI |
| IDT70V9159L9PFI | IDT70V9359S7PF | IDT7130VL55TFGI | IDT7133LA55PF |
| IDT70V9169L6PF | IDT70V9359S9PF | IDT7130VL55TFI | IDT7133LA55PFG |
| IDT70V9169L7PF | IDT70V9369L12PF | IDT71321LA20PF | IDT7133LA55PFI |
| IDT70V9169L7PFI | IDT70V9369L6PF | IDT71321LA20PFG | IDT7133SA20PF |
| IDT70V9169L9PF | IDT70V9369L7PF | IDT71321LA20TF | IDT7133SA25PF |
| IDT70V9169L9PFI | IDT70V9369L7PFI | IDT71321LA20TFG | IDT7133SA25PFG |
| IDT70V9179L12PF | IDT70V9369L9PF | IDT71321LA25PF | IDT7133SA25PFI |
| IDT70V9179L7PF | IDT70V9369L9PFI | IDT71321LA25PFG | IDT7133SA35PF |
| IDT70V9179L9PF | IDT70V9389L7PF | IDT71321LA25PFGI | IDT7133SA35PFG |
| IDT70V9179L9PFI | IDT7130L25TFI | IDT71321LA25PFI | IDT7133SA35PFGI |
| IDT70V9189L12PF | IDT7130LA100PF | IDT71321LA25TF | IDT7133SA55PF |
| IDT70V9189L12PFI | IDT7130LA20PF | IDT71321LA25TFI | IDT7133SA55PFG |
| IDT70V9189L7PF | IDT7130LA20PFG | IDT71321LA35PF | IDT7133SA55PFI |
| IDT70V9189L7PFI | IDT7130LA20TF | IDT71321LA35PFG | IDT71342LA20PF |
| IDT70V9189L9PF | IDT7130LA20TFG | IDT71321LA35PFI | IDT71342LA20PFG |
| IDT70V9189L9PFI | IDT7130LA25PF | IDT71321LA35TF | IDT71342LA25PF |
| IDT70V9199L12PF | IDT7130LA25PFGI | IDT71321LA35TFI | IDT71342LA25PFGI |
| IDT70V9199L12PFI | IDT7130LA25PFI | IDT71321LA55PF | IDT71342LA25PFI |
| IDT70V9199L7PF | IDT7130LA25TF | IDT71321LA55PFG | IDT71342LA35PF |
| IDT70V9199L7PFG | IDT7130LA25TFG | IDT71321LA55PFI | IDT71342LA55PF |
| IDT70V9199L7PFI | IDT7130LA25TFGI | IDT71321LA55TF | IDT71342LA55PFG |
| IDT70V9199L9PF | IDT7130LA25TFI | IDT71321LA55TFG | IDT71342LA55PFGI |
| IDT70V9199L9PFI | IDT7130LA35PF | IDT71321SA20PF | IDT71342LA55PFI |
| IDT70V9269L7PF | IDT7130LA35TF | IDT71321SA20TF | IDT71342SA20PF |
| IDT70V9289L12PF | IDT7130LA35TFG | IDT71321SA25PF | IDT71342SA25PF |
| IDT70V9289L6PF | IDT7130LA45TFI | IDT71321SA25PFG | IDT71342SA25PFI |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|------------------|-----------------|------------------|
| IDT71342SA35PF | IDT71V30L35TFI | IDT71V321S55TFG | IDT72221L25PF |
| IDT71342SA55PF | IDT71V30L55TF | IDT71V321SA25PF | IDT72221L25PFI |
| IDT71342SA55PFI | IDT71V30L55TFI | IDT71V321SA35PF | IDT72225LB10PF |
| IDT7140LA100PF | IDT71V30S25TF | IDT71V321SA45PF | IDT72225LB10PFG |
| IDT7140LA20PF | IDT71V30S25TFG | IDT71V321SA55PF | IDT72225LB10TF |
| IDT7140LA20PFG | IDT71V30S25TFI | IDT72201L10PF | IDT72225LB15PF |
| IDT7140LA25PF | IDT71V30S35TF | IDT72201L10PFG | IDT72225LB15PFG |
| IDT7140LA25PFGI | IDT71V30S35TFGI | IDT72201L15PF | IDT72225LB15PFGI |
| IDT7140LA25PFI | IDT71V30S35TFI | IDT72201L15PFI | IDT72225LB15PFI |
| IDT7140LA35PF | IDT71V30S55TF | IDT72201L25PF | IDT72225LB15TF |
| IDT7140LA55PF | IDT71V30S55TFG | IDT72201L25PFI | IDT72225LB15TFI |
| IDT7140SA100PF | IDT71V30VL55TFI | IDT72205LB10PF | IDT72225LB20PF |
| IDT7140SA20PF | IDT71V30VL90TF | IDT72205LB10TF | IDT72225LB25PF |
| IDT7140SA25PF | IDT71V321L25PF | IDT72205LB15PF | IDT72225LB25PFG |
| IDT7140SA35PF | IDT71V321L25PFG | IDT72205LB15PFI | IDT72225LB25PFI |
| IDT7140SA35PFI | IDT71V321L25PFGI | IDT72205LB15TF | IDT72225LB25TF |
| IDT7140SA55PF | IDT71V321L25PFI | IDT72205LB15TFI | IDT72225LB25TFI |
| IDT71421LA20PF | IDT71V321L25TF | IDT72205LB25PF | IDT72231L10PF |
| IDT71421LA25PF | IDT71V321L25TFG | IDT72205LB25PFI | IDT72231L15PF |
| IDT71421LA25PFI | IDT71V321L25TFGI | IDT72205LB25TF | IDT72231L15PFI |
| IDT71421LA35PF | IDT71V321L25TFI | IDT72205LB25TFI | IDT72231L25PF |
| IDT71421LA55PF | IDT71V321L35PF | IDT72211L10PF | IDT72231L25PFI |
| IDT71421LA55PFG | IDT71V321L35TF | IDT72211L10PFG | IDT72235LB10PF |
| IDT71421LA55PFI | IDT71V321L55PF | IDT72211L15PF | IDT72235LB10TF |
| IDT71421SA20PF | IDT71V321L55PFG | IDT72211L15PFG | IDT72235LB10TFG |
| IDT71421SA25PF | IDT71V321L55PFGI | IDT72211L15PFGI | IDT72235LB15PF |
| IDT71421SA35PF | IDT71V321L55PFI | IDT72211L15PFI | IDT72235LB15PFG |
| IDT71421SA35PFI | IDT71V321L55TF | IDT72211L25PF | IDT72235LB15PFI |
| IDT71421SA55PF | IDT71V321L55TFG | IDT72211L25PFG | IDT72235LB15TF |
| IDT7143LA20PF | IDT71V321L55TFGI | IDT72211L25PFI | IDT72235LB15TFI |
| IDT7143LA20PFG | IDT71V321L55TFI | IDT72215LB10PF | IDT72235LB25PF |
| IDT7143LA25PF | IDT71V321LA25PF | IDT72215LB10PFG | IDT72235LB25PFG |
| IDT7143LA25PFI | IDT71V321LA35PF | IDT72215LB10TF | IDT72235LB25PFI |
| IDT7143LA35PF | IDT71V321LA45PF | IDT72215LB15PF | IDT72235LB25TF |
| IDT7143LA55PF | IDT71V321LA55PF | IDT72215LB15PFI | IDT72235LB25TFI |
| IDT7143SA20PF | IDT71V321S25PF | IDT72215LB15TF | IDT72241L10PF |
| IDT7143SA25PF | IDT71V321S25PFG | IDT72215LB15TFI | IDT72241L15PF |
| IDT7143SA35PF | IDT71V321S25PFI | IDT72215LB25PF | IDT72241L15PFI |
| IDT7143SA55PF | IDT71V321S25TF | IDT72215LB25PFI | IDT72241L25PF |
| IDT71V30L25TF | IDT71V321S35PF | IDT72215LB25TF | IDT72241L25PFI |
| IDT71V30L25TFG | IDT71V321S35TF | IDT72215LB25TFI | IDT72245LB10PF |
| IDT71V30L25TFI | IDT71V321S55PF | IDT72221L10PF | IDT72245LB10PFG |
| IDT71V30L35TF | IDT71V321S55PFI | IDT72221L15PF | IDT72245LB10TF |
| IDT71V30L35TFGI | IDT71V321S55TF | IDT72221L15PFI | IDT72245LB10TFG |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-----------------|-----------------|-----------------|
| IDT72245LB15PF | IDT72265LA10TFG | IDT72285L10PFG | IDT723642L12PF |
| IDT72245LB15PFG | IDT72265LA15PF | IDT72285L10TF | IDT723642L15PF |
| IDT72245LB15PFI | IDT72265LA15PFI | IDT72285L10TFG | IDT723651L15PF |
| IDT72245LB15TF | IDT72265LA15TF | IDT72285L15PF | IDT723651L20PF |
| IDT72245LB15TFI | IDT72265LA15TFI | IDT72285L15PFGI | IDT723651L20PFI |
| IDT72245LB20PF | IDT72265LA20PF | IDT72285L15PFI | IDT723652L12PF |
| IDT72245LB25PF | IDT72265LA20PFI | IDT72285L15TF | IDT723652L15PF |
| IDT72245LB25PFI | IDT72265LA20TF | IDT72285L15TFI | IDT723662L12PF |
| IDT72245LB25TF | IDT72265LA20TFI | IDT72285L20PF | IDT723662L15PF |
| IDT72245LB25TFI | IDT72271LA10PF | IDT72285L20PFI | IDT723672L12PF |
| IDT72251L10PF | IDT72271LA10PFG | IDT72285L20TF | IDT723672L15PF |
| IDT72251L10PFG | IDT72271LA10TF | IDT72285L20TFI | IDT72421L10PF |
| IDT72251L15PF | IDT72271LA15PF | IDT72291L10PF | IDT72421L15PF |
| IDT72251L15PFI | IDT72271LA15PFI | IDT72291L10TF | IDT72421L15PFI |
| IDT72251L25PF | IDT72271LA15TF | IDT72291L15PF | IDT72421L25PF |
| IDT72251L25PFI | IDT72271LA15TFI | IDT72291L15PFI | IDT72421L25PFI |
| IDT72255LA10PF | IDT72271LA20PF | IDT72291L15TF | IDT72605L20PF |
| IDT72255LA10PFG | IDT72271LA20PFI | IDT72291L15TFI | IDT72605L20PFG |
| IDT72255LA10TF | IDT72271LA20TF | IDT72291L20PF | IDT72605L25PF |
| IDT72255LA10TFG | IDT72271LA20TFI | IDT72291L20PFI | IDT72605L35PF |
| IDT72255LA15PF | IDT72275L10PF | IDT72291L20TF | IDT72605L50PF |
| IDT72255LA15PFG | IDT72275L10PFG | IDT72291L20TFI | IDT72615L20PF |
| IDT72255LA15PFGI | IDT72275L10TF | IDT723611L15PF | IDT72615L25PF |
| IDT72255LA15PFI | IDT72275L10TFG | IDT723611L20PF | IDT72615L35PF |
| IDT72255LA15TF | IDT72275L15PF | IDT723611L20PFI | IDT72615L50PF |
| IDT72255LA15TFI | IDT72275L15PFI | IDT723612L15PF | IDT72801L10PF |
| IDT72255LA20PF | IDT72275L15TF | IDT723612L20PF | IDT72801L10PFG |
| IDT72255LA20PFI | IDT72275L15TFI | IDT723612L20PFI | IDT72801L10TF |
| IDT72255LA20TF | IDT72275L20PF | IDT723613L15PF | IDT72801L15PF |
| IDT72255LA20TFI | IDT72275L20PFI | IDT723613L20PF | IDT72801L15PFG |
| IDT72261LA10PF | IDT72275L20TF | IDT723613L20PFI | IDT72801L15PFI |
| IDT72261LA10TF | IDT72275L20TFI | IDT723614L15PF | IDT72801L15TF |
| IDT72261LA15PF | IDT72281L10PF | IDT723614L20PF | IDT72801L15TFI |
| IDT72261LA15PFI | IDT72281L10PFG | IDT723614L20PFI | IDT72801L25PF |
| IDT72261LA15TF | IDT72281L10TF | IDT723622L12PF | IDT72801L25PFG |
| IDT72261LA15TFGI | IDT72281L15PF | IDT723622L15PF | IDT72801L25PFI |
| IDT72261LA15TFI | IDT72281L15PFI | IDT723631L15PF | IDT72801L25TF |
| IDT72261LA20PF | IDT72281L15TF | IDT723631L20PF | IDT72801L25TFI |
| IDT72261LA20PFI | IDT72281L15TFI | IDT723631L20PFI | IDT72811L10PF |
| IDT72261LA20TF | IDT72281L20PF | IDT723632L12PF | IDT72811L10PFG |
| IDT72261LA20TFI | IDT72281L20PFI | IDT723632L15PF | IDT72811L10TF |
| IDT72265LA10PF | IDT72281L20TF | IDT723641L15PF | IDT72811L15PF |
| IDT72265LA10PFG | IDT72281L20TFI | IDT723641L20PF | IDT72811L15PFG |
| IDT72265LA10TF | IDT72285L10PF | IDT723641L20PFI | IDT72811L15PFI |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|-------------------|--------------------|------------------|
| IDT72811L15TF | IDT72851L15PFI | IDT72V205L20PF | IDT72V215L15TF |
| IDT72811L15TFI | IDT72851L15TF | IDT72V205L20TF | IDT72V215L15TFG |
| IDT72811L25PF | IDT72851L15TFI | IDT72V2101L10PF | IDT72V215L15TFI |
| IDT72811L25PFG | IDT72851L25PF | IDT72V2101L15PF | IDT72V215L20PF |
| IDT72811L25PFI | IDT72851L25PFI | IDT72V2101L15PFI | IDT72V215L20TF |
| IDT72811L25TF | IDT72851L25TF | IDT72V2101L20PF | IDT72V221L10PF |
| IDT72811L25TFI | IDT72851L25TFI | IDT72V2103L10PF | IDT72V221L10PFG |
| IDT72821L10PF | IDT728981DB | IDT72V2103L10PFI | IDT72V221L15PF |
| IDT72821L10PFG | IDT72V10071L15TFI | IDT72V2103L15PF | IDT72V221L15PFG |
| IDT72821L10TF | IDT72V10081L15PFI | IDT72V2103L15PFG | IDT72V221L15PFI |
| IDT72821L15PF | IDT72V110163L10PF | IDT72V2103L6PF | IDT72V221L20PF |
| IDT72821L15PFI | IDT72V11071L15TFI | IDT72V2103L6PFG | IDT72V223L6PF |
| IDT72821L15TF | IDT72V11081L15PFI | IDT72V2103L7-5PF | IDT72V223L6PFG |
| IDT72821L15TFI | IDT72V11165L15TFI | IDT72V2105L10PF | IDT72V223L7-5PF |
| IDT72821L25PF | IDT72V12071L15TFI | IDT72V2105L10PFG | IDT72V223L7-5PFI |
| IDT72821L25PFI | IDT72V12081L15PFI | IDT72V2105L15PF | IDT72V225L10PF |
| IDT72821L25TF | IDT72V12165L15TFI | IDT72V2105L15PFGI | IDT72V225L10PFG |
| IDT72821L25TFI | IDT72V13071L15TFI | IDT72V2105L15PFI | IDT72V225L10TF |
| IDT72831L10PF | IDT72V13081L15PFI | IDT72V2105L20PF | IDT72V225L10TFG |
| IDT72831L10PFG | IDT72V13165L15TFI | IDT72V2111L10PF | IDT72V225L15PF |
| IDT72831L10TF | IDT72V14071L15TFI | IDT72V2111L10PFG | IDT72V225L15PFI |
| IDT72831L15PF | IDT72V14081L15PFI | IDT72V2111L15PF | IDT72V225L15TF |
| IDT72831L15PFI | IDT72V14165L15TFI | IDT72V2111L15PFI | IDT72V225L15TFI |
| IDT72831L15TF | IDT72V15160L10PFI | IDT72V2111L20PF | IDT72V225L20PF |
| IDT72831L15TFI | IDT72V15165L15TFI | IDT72V2113L10PF | IDT72V225L20TF |
| IDT72831L25PF | IDT72V16160L10PFI | IDT72V2113L10PFI | IDT72V225L20TFG |
| IDT72831L25PFI | IDT72V17160L10PFI | IDT72V2113L15PF | IDT72V231L10PF |
| IDT72831L25TF | IDT72V18160L10PFI | IDT72V2113L15PFG | IDT72V231L10PFG |
| IDT72831L25TFI | IDT72V19160L10PFI | IDT72V2113L6PF | IDT72V231L15PF |
| IDT72841L10PF | IDT72V201L10PF | IDT72V2113L6PFG | IDT72V231L15PFGI |
| IDT72841L10PFG | IDT72V201L10PFG | IDT72V2113L7-5PF | IDT72V231L15PFI |
| IDT72841L10TF | IDT72V201L15PF | IDT72V2113L7-5PFGI | IDT72V231L20PF |
| IDT72841L15PF | IDT72V201L15PFI | IDT72V211L10PF | IDT72V231L20PFG |
| IDT72841L15PFG | IDT72V201L20PF | IDT72V211L10PFG | IDT72V233L6PF |
| IDT72841L15PFI | IDT72V205L10PF | IDT72V211L15PF | IDT72V233L7-5PF |
| IDT72841L15TF | IDT72V205L10PFG | IDT72V211L15PFG | IDT72V233L7-5PFI |
| IDT72841L15TFI | IDT72V205L10TF | IDT72V211L15PFGI | IDT72V235L10PF |
| IDT72841L25PF | IDT72V205L10TFG | IDT72V211L15PFI | IDT72V235L10PFG |
| IDT72841L25PFI | IDT72V205L15PF | IDT72V211L20PF | IDT72V235L10TF |
| IDT72841L25TF | IDT72V205L15PFGI | IDT72V215L10PF | IDT72V235L10TFG |
| IDT72841L25TFI | IDT72V205L15PFI | IDT72V215L10TF | IDT72V235L15PF |
| IDT72851L10PF | IDT72V205L15TF | IDT72V215L10TFG | IDT72V235L15PFG |
| IDT72851L10TF | IDT72V205L15TFG | IDT72V215L15PF | IDT72V235L15PFI |
| IDT72851L15PF | IDT72V205L15TFI | IDT72V215L15PFI | IDT72V235L15TF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-------------------|-------------------|-------------------|
| IDT72V235L15TFI | IDT72V255LA15TFG | IDT72V273L15PF | IDT72V285L20PF |
| IDT72V235L20PF | IDT72V255LA15TFGI | IDT72V273L6PF | IDT72V285L20TF |
| IDT72V235L20TF | IDT72V255LA15TFI | IDT72V273L7-5PF | IDT72V291L10PF |
| IDT72V241L10PF | IDT72V255LA20PF | IDT72V273L7-5PFGI | IDT72V291L10TF |
| IDT72V241L10PFG | IDT72V255LA20TF | IDT72V273L7-5PFI | IDT72V291L10TFG |
| IDT72V241L15PF | IDT72V261LA10PF | IDT72V275L10PF | IDT72V291L15PF |
| IDT72V241L15PFG | IDT72V261LA10PFG | IDT72V275L10PFG | IDT72V291L15PFI |
| IDT72V241L15PFGI | IDT72V261LA10TF | IDT72V275L10TF | IDT72V291L15TF |
| IDT72V241L15PFI | IDT72V261LA15PF | IDT72V275L15PF | IDT72V291L15TFI |
| IDT72V241L20PF | IDT72V261LA15PFI | IDT72V275L15PFG | IDT72V291L20PF |
| IDT72V243L6PF | IDT72V261LA15TF | IDT72V275L15PFGI | IDT72V291L20TF |
| IDT72V243L7-5PF | IDT72V261LA15TFI | IDT72V275L15PFI | IDT72V293L10PF |
| IDT72V243L7-5PFI | IDT72V261LA20PF | IDT72V275L15TF | IDT72V293L10PFI |
| IDT72V245L10PF | IDT72V261LA20TF | IDT72V275L15TFI | IDT72V293L15PF |
| IDT72V245L10PFG | IDT72V263L10PF | IDT72V275L20PF | IDT72V293L6PF |
| IDT72V245L10TF | IDT72V263L10PFI | IDT72V275L20TF | IDT72V293L6PFG |
| IDT72V245L10TFG | IDT72V263L15PF | IDT72V281L10PF | IDT72V293L7-5PF |
| IDT72V245L15PF | IDT72V263L6PF | IDT72V281L10PFG | IDT72V293L7-5PFGI |
| IDT72V245L15PFG | IDT72V263L6PFG | IDT72V281L10TF | IDT72V293L7-5PFI |
| IDT72V245L15PFGI | IDT72V263L7-5PF | IDT72V281L15PF | IDT72V295L10PF |
| IDT72V245L15PFI | IDT72V263L7-5PFI | IDT72V281L15PFG | IDT72V295L10PFG |
| IDT72V245L15TF | IDT72V265LA10PF | IDT72V281L15PFGI | IDT72V295L15PF |
| IDT72V245L15TFG | IDT72V265LA10PFG | IDT72V281L15PFI | IDT72V295L15PFGI |
| IDT72V245L15TFGI | IDT72V265LA10TF | IDT72V281L15TF | IDT72V295L15PFI |
| IDT72V245L15TFI | IDT72V265LA10TFG | IDT72V281L15TFI | IDT72V295L20PF |
| IDT72V245L20PF | IDT72V265LA15PF | IDT72V281L20PF | IDT72V36102L10PF |
| IDT72V245L20TF | IDT72V265LA15PFI | IDT72V281L20PFG | IDT72V36102L10PFI |
| IDT72V251L10PF | IDT72V265LA15TF | IDT72V281L20TF | IDT72V36102L15PF |
| IDT72V251L10PFG | IDT72V265LA15TFGI | IDT72V283L10PF | IDT72V3611L12PF |
| IDT72V251L15PF | IDT72V265LA15TFI | IDT72V283L10PFI | IDT72V3611L15PF |
| IDT72V251L15PFGI | IDT72V265LA20PF | IDT72V283L15PF | IDT72V3611L20PF |
| IDT72V251L15PFI | IDT72V265LA20TF | IDT72V283L6PF | IDT72V3612L12PF |
| IDT72V251L20PF | IDT72V271LA10PF | IDT72V283L6PFG | IDT72V3612L15PF |
| IDT72V253L6PF | IDT72V271LA10PFG | IDT72V283L7-5PF | IDT72V3612L20PF |
| IDT72V253L7-5PF | IDT72V271LA10TF | IDT72V283L7-5PFGI | IDT72V3613L12PF |
| IDT72V253L7-5PFI | IDT72V271LA15PF | IDT72V283L7-5PFI | IDT72V3613L15PF |
| IDT72V255LA10PF | IDT72V271LA15PFI | IDT72V285L10PF | IDT72V3613L20PF |
| IDT72V255LA10PFG | IDT72V271LA15TF | IDT72V285L10PFG | IDT72V3614L12PF |
| IDT72V255LA10TF | IDT72V271LA15TFI | IDT72V285L10TF | IDT72V3614L15PF |
| IDT72V255LA10TFG | IDT72V271LA20PF | IDT72V285L10TFG | IDT72V3614L20PF |
| IDT72V255LA15PF | IDT72V271LA20TF | IDT72V285L15PF | IDT72V3622L10PF |
| IDT72V255LA15PFG | IDT72V273L10PF | IDT72V285L15PFI | IDT72V3622L15PF |
| IDT72V255LA15PFI | IDT72V273L10PFG | IDT72V285L15TF | IDT72V3631L15PF |
| IDT72V255LA15TF | IDT72V273L10PFI | IDT72V285L15TFI | IDT72V3631L20PF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|------------------|---------------------|-------------------|
| IDT72V3632L10PF | IDT72V811L10PFG | IDT72V851L15TFI | IDT82V3255TFG |
| IDT72V3632L15PF | IDT72V811L10TF | IDT72V851L20PF | IDT82V3280DQ |
| IDT72V3641L15PF | IDT72V811L15PF | IDT72V851L20TF | IDT82V3280PF |
| IDT72V3641L20PF | IDT72V811L15PFG | IDT72V90823PF | IDT82V3280PFG |
| IDT72V3642L10PF | IDT72V811L15PFI | IDT72V90823PFG | ICS8312AY |
| IDT72V3642L15PF | IDT72V811L15TF | IDT74SSTV16859NLG | ICS8312AYI |
| IDT72V3642L15PFI | IDT72V811L15TFI | IDT74SSTVF16859NLG | ICS8312AYILF |
| IDT72V3651L15PF | IDT72V811L20PF | IDT74SSTVN16859CNLG | ICS8312AYLF |
| IDT72V3651L20PF | IDT72V811L20TF | IDT74SSTVN16859NLG | ICS8343AY-01 |
| IDT72V3652L10PF | IDT72V821L10PF | IDT77V106L25TF | ICS8343AY-01LF |
| IDT72V3652L15PF | IDT72V821L10TF | IDT77V106L25TFGI | ICS8343AYI-01 |
| IDT72V3662L10PF | IDT72V821L15PF | IDT77V126L200TF | ICS8343YI |
| IDT72V3662L15PF | IDT72V821L15PFI | IDT77V500S25PF | ICS83940AY-02 |
| IDT72V3672L10PF | IDT72V821L15TF | IDT77V500S27PF | ICS83940AY-02LF |
| IDT72V3672L15PF | IDT72V821L15TFI | IDT79R3041-20PF | ICS83940BY |
| IDT72V3672L15PFI | IDT72V821L20PF | IDT79R3041-20PFG | ICS83940BYLF |
| IDT72V3682L10PF | IDT72V821L20TF | IDT79R3041-25PF | ICS83940DY |
| IDT72V3682L15PF | IDT72V831L10PF | IDT79R3041-25PFG | ICS83940DY-01 |
| IDT72V3692L10PF | IDT72V831L10PFG | IDT79R3041-33PF | ICS83940DY-01LF |
| IDT72V3692L15PF | IDT72V831L10TF | IDT79R3041-33PFG | ICS83940DYI |
| IDT72V70180PF | IDT72V831L15PF | IDT821024PP | ICS83940DYI-01 |
| IDT72V70180PFG | IDT72V831L15PFI | IDT821024PPG | ICS83940DYI-01LF |
| IDT72V70190PF | IDT72V831L15TF | IDT821034DN | ICS83940DYLF |
| IDT72V70190PFG | IDT72V831L15TFI | IDT821054APF | ICS83940LYI |
| IDT72V70200PF | IDT72V831L20PF | IDT821054APFG | ICS83947AYI |
| IDT72V70200PFG | IDT72V831L20TF | IDT821054PQF | ICS83947AYI-147 |
| IDT72V70800PF | IDT72V841L10PF | IDT82P2281PF | ICS83947AYI-147LF |
| IDT72V70800PFG | IDT72V841L10PFG | IDT82P2281PFG | ICS83947AYILN |
| IDT72V70800TF | IDT72V841L10TF | IDT82V1054APF | ICS83948AYI |
| IDT72V70800TFG | IDT72V841L10TFG | IDT82V1054APFG | ICS83948AYI-01 |
| IDT72V70810PF | IDT72V841L15PF | IDT82V2041EPP | ICS83948AYI-01LF |
| IDT72V70810PFG | IDT72V841L15PFG | IDT82V2041EPPG | ICS83948AYI-147 |
| IDT72V70810TF | IDT72V841L15PFI | IDT82V2042EPF | ICS83948AYI-147LF |
| IDT72V70810TFG | IDT72V841L15TF | IDT82V2042EPFG | ICS83948AYILF |
| IDT72V801L10PF | IDT72V841L15TFGI | IDT82V2051EPP | ICS84021AY |
| IDT72V801L10PFG | IDT72V841L15TFI | IDT82V2051EPPG | ICS84021AYLF |
| IDT72V801L10TF | IDT72V841L20PF | IDT82V2052EPF | ICS8402AY |
| IDT72V801L15PF | IDT72V841L20TF | IDT82V2052EPFG | ICS8402AYI |
| IDT72V801L15PFI | IDT72V851L10PF | IDT82V2081PP | ICS8402AYILF |
| IDT72V801L15TF | IDT72V851L10PFG | IDT82V2081PPG | ICS8402AYLF |
| IDT72V801L15TFI | IDT72V851L10TF | IDT82V2082PF | ICS8427DY-02 |
| IDT72V801L20PF | IDT72V851L15PF | IDT82V2082PFG | ICS8427DY-02LF |
| IDT72V801L20TF | IDT72V851L15PFI | IDT82V3255DK | ICS843020AY-01 |
| IDT72V811L10PF | IDT72V851L15TF | IDT82V3255TF | ICS843020AY-01LF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-------------------|-------------------|-------------------|
| ICS8430AY-61 | ICS84330AY-03 | ICS8624BYI | ICS87951AYI |
| ICS8430AY-61LF | ICS84330AY-03LF | ICS8624BYILF | ICS87951AYI-147 |
| ICS8430AY-71 | ICS84330BY | ICS8624BYLF | ICS87951AYI-147LF |
| ICS8430AYI-61 | ICS84330BYLF | ICS8634BY-01 | ICS87951AYILF |
| ICS8430AYI-61LF | ICS84330BYLN | ICS8634BY-01LF | ICS87952AY-147 |
| ICS8430AYI-71 | ICS84330CY | ICS86953BYI | ICS87952AY-147LF |
| ICS8430AYI-71LF | ICS84330CYI | ICS86953BYI-147 | ICS87952AYI-147 |
| ICS8430BY-71 | ICS84330CYLN | ICS86953BYI-20 | ICS87952AYI-147LF |
| ICS8430BY-71LF | ICS844008AY-16 | ICS86962CYI-01 | ICS87993AYI |
| ICS8430BYI-71LF | ICS844008AYI-15 | ICS8705BY | ICS87993AYILF |
| ICS8430DY-111 | ICS844008AYI-15LF | ICS8705BYI | ICS9281BYLF |
| ICS8430DY-111LF | ICS844008AYI-15TT | ICS8705BYILF | ICS932S309CK |
| ICS8430EY-01 | ICS8442AY | ICS8705BYLF | ICS932S803AYLF |
| ICS8430EY-01LF | ICS8442AYI | ICS8725AY-01 | ICS93V857BK-130 |
| ICS8430EY-11 | ICS8442AYILF | ICS8725AY-01LF | ICS952909AKLF |
| ICS8430EY-11LF | ICS8442AYLF | ICS8725AYI-01 | ICS954226AKLF |
| ICS8430EYI-01 | ICS85210AY-21 | ICS8733BY-01 | ICS954305DKLF |
| ICS8430EYI-11 | ICS85210AY-31 | ICS8733BY-01LF | ICS954305EKLF |
| ICS84314AY | ICS85210AY-31LF | ICS8735AY-01 | ICS954309BKLF |
| ICS84314AY-01 | ICS8521AYI-03 | ICS8735AY-01LF | ICS95V2F857AK |
| ICS84314AY-02 | ICS8521AYI-03LN | ICS8735AY-31 | ICS95V2F857AKLF |
| ICS84314AY-02LF | ICS8521BY | ICS8735AYI-01 | ICS95V857AK |
| ICS84314AYLF | ICS8521BYI | ICS8735AYI-31 | ICS95V857AK-130 |
| ICS84314BY | ICS8521BYILF | ICS8745BY | ICS95V857AK-130LF |
| ICS843202AYI | ICS8521BYLF | ICS8745BYI | ICS95V857AKLF |
| ICS843202AYILF | ICS8521BYLN | ICS8745BYLF | ICS95V857CK |
| ICS84320AY-01 | ICS853031AY | ICS8752CY | ICS95V857CKLF |
| ICS84320AY-01LN | ICS853031AYLF | ICS8752CYI | ICS95VLP857AK |
| ICS84320AYI-01 | ICS85310AYI-01 | ICS8752CYLF | ICS95VLP857AKLF |
| ICS84321AY | ICS85310AYI-01LF | ICS87608AYI | ICS95VLP857AK |
| ICS84321AYI | ICS85310AYI-01LN | ICS87608AYILF | ICS97U870AK |
| ICS84321AYLF | ICS85310AYI-11 | ICS8761CY | ICS97U870AKI |
| ICS84329BY | ICS85310AYI-21 | ICS8761CYI | ICS97U877AK |
| ICS84329BYLF | ICS85310AYI-21LN | ICS8761CYILF | ICS97U877AKI |
| ICS8432BY-51 | ICS85310AYI-31 | ICS8761CYLF | ICS97U877AKLF |
| ICS8432BY-51LF | ICS853111AY | ICS8761CYLN | ICS97ULP877AK |
| ICS8432BYI-51 | ICS853111AYLF | ICS87931BYI | ICS97ULP877AKLF |
| ICS8432CY-11 | ICS8531AY-01 | ICS87946AYI | ICS97ULP877BK |
| ICS8432CY-111 | ICS8531AY-01LF | ICS87946AYI-01 | ICS97ULP877BKLF |
| ICS8432CY-111LF | ICS853210AY | ICS87946AYI-147 | ICS97ULP878AK |
| ICS8432DY-101 | ICS853210BY | ICS87946AYI-147LF | ICS97ULP878AKLF |
| ICS8432DY-101LF | ICS854210CY | ICS87946AYILF | ICS97ULP878BK |
| ICS8432DYI-101 | ICS8602BY | ICS87950BYI | ICS97ULP878BKLF |
| ICS8432DYI-101LF | ICS8624BY | ICS87950BYILF | ICS98ULPA877AKLF |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN #: TB-0609-03

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|---------------|-------------|-------------------|
| ICS9FG1900AK-1LF | IDTCV150NLG | MPC92439FA | MPC9448AC |
| ICS9FG1901CK | IDTCV153NLG | MPC92469AC | MPC9448FA |
| ICS9FG1901CKLF | IDTCV155NLG | MPC92469FA | MPC9456AC |
| ICS9FG1901EKLF | IDTCV164NLG | MPC930FA | MPC9456FA |
| ICS9FG1902AK | IDTCV168NLG | MPC9315AC | MPC9608AC |
| ICS9FG1902AKLF | IDTCV169CNLG | MPC9315FA | MPC9608FA |
| ICS9FG1903AK-1LF | IDTCV169NLG | MPC9330AC | MPC961CAC |
| ICS9FG1903AK-2LF | IDTCV171NLG | MPC9330FA | MPC961CFA |
| ICS9FG1903AKLF | IDTCV179ANLG | MPC9331AC | MPC961PAC |
| ICS9FGP201BKLF | IDTCV180ANLG | MPC9331FA | MPC961PFA |
| ICS9LP505-2HKLF | MC100ES6111AC | MPC9350AC | MPC9653AAC |
| ICS9LPR309AKLF | MC100ES6111FA | MPC9350FA | MPC9653AFA |
| ICS9LPR309BKLF | MC100ES6210AC | MPC9351AC | MPC9658AC |
| ICS9LPR311AKLF | MC100ES6210FA | MPC9351FA | MPC9658FA |
| ICS9LPR311BKLF | MC100ES6226AC | MPC9352AC | MPC9824FA |
| ICS9LPR321BKLF | MC100ES6226FA | MPC9352FA | MPC9992AC |
| ICS9LPR323AKLF | MC100ES6254AC | MPC93H51AC | MPC9992FA |
| ICS9LPR325CKLF | MC100ES6254FA | MPC93H51FA | MPC9993AC |
| ICS9LPR333AKLF | MC100ES8014DT | MPC93H52AC | MPC9993FA |
| ICS9LPR335BKLF | MC100ES8111AC | MPC93H52FA | MPC99J93AC |
| ICS9LPR800BKLF | MC100ES8111FA | MPC93R51AC | MPC99J93FA |
| ICS9LPRS228CKLF | MC12429FA | MPC93R51FA | ICSSSTV16859CK |
| ICS9LPRS319BKLF | MC12430FA | MPC93R52AC | ICSSSTV16859CKLF |
| ICS9LPRS319CKLF | MPC9109AC | MPC93R52FA | ICSSSTVA16859AK |
| ICS9LPRS325CKLF | MPC9109FA | MPC940LAC | ICSSSTVA16859AKLF |
| ICS9LPRS333AKLF | MPC9229AC | MPC940LFA | ICSSSTVA16859BK |
| ICS9LPRS355AKLF | MPC9229FA | MPC942CAC | ICSSSTVA16859BKLF |
| ICCLK503J45KLF | MPC9230AC | MPC942CFA | ICSSSTVA16859CK |
| IDTCSPT857CNLG | MPC9230FA | MPC942PAC | ICSSSTVA16859CKLF |
| IDTCSPT857DNLG | MPC9239AC | MPC942PFA | ICSSSTVA16859DKLF |
| IDTCSPU877ANLG | MPC9239FA | MPC9446AC | ICSSSTVF16859AK |
| IDTCSPU877DNLG | MPC92429AC | MPC9446FA | ICSSSTVF16859BK |
| IDTCSPUA877ANLG | MPC92429FA | MPC9447AC | ICSSSTVF16859BKLF |
| IDTCV145NLG | MPC92439AC | MPC9447FA | |

Notes: For T & R (shipping method) "8" is added to the IDT p/n and "T" is added to the ICS p/n.