



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE # CQ-14-06

ISSUE DATE: July 31, 2014

LAST TIME BUY DATE: July 31, 2015

LAST TIME SHIP DATE: October 31, 2015

REASON FOR DISCONTINUANCE:

Manufacturing related issues requires IDT to discontinue the attached list of products.

Some of these products may have an alternate IDT part number as a drop in replacement or a suggested functional replacement.

Customer should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuation Notice. They may also contact their local IDT Sales Office listed on the IDT website at www.idt.com or the Marketing contact listed below. The affected parts lists show the applicable product marketing group.

<u>Product Group</u>	<u>Product Group Contact Information</u>
MMT	Victory Abarca (Victor.Abarca@idt.com) Phone# (408) 284-6578
SPO	Carl May (Carl.May@idt.com) Phone (408) 284-2718
NWC	clocks@idt.com
MIP	Paul Barton (Paul.Barton@idt.com) Phone (408) 284-8306
ACP	Matt Jones (Matt.Jones@idt.com) Phone (408) 360-5622

Last time buy orders may be submitted any time prior to the last time buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Reason for Discontinuance	Replacement Part Availability	Product Group	Notes
1526GILF	-	-	Fab Closure	N/A	MMT	
1526GILFT	-	-	Fab Closure	N/A	MMT	
1526GLF	-	-	Fab Closure	N/A	MMT	
1526GLFT	-	-	Fab Closure	N/A	MMT	
5962-8952301EA	-	-	Fab Closure	N/A	SPO	
5962-8952304EA	-	-	Fab Closure	N/A	SPO	
5962-8952305EA	-	-	Fab Closure	N/A	SPO	
5962-8952306EA	-	-	Fab Closure	N/A	SPO	
5962-8952307EA	-	-	Fab Closure	N/A	SPO	
5962-8952308EA	-	-	Fab Closure	N/A	SPO	
5T93GL10NLGI	-	854110AKILF	Fab closure	Now	NWC	Note 1
5T93GL10NLGI8	-	854110AKILFT	Fab closure	Now	NWC	Note 1
671AGI-28LF	-	-	Fab closure	N/A	MMT	
671AGI-28LFT	-	-	Fab closure	N/A	MMT	
671AGI-38LF	-	-	Fab closure	N/A	MMT	
671AGI-38LFT	-	-	Fab closure	N/A	MMT	
6V10035DCG	-	-	Fab Closure	N/A	MMT	
6V10035DCG8	-	-	Fab Closure	N/A	MMT	
6V10035DCGI	-	-	Fab Closure	N/A	MMT	
6V10035DCGI8	-	-	Fab Closure	N/A	MMT	
6V40277DCGI	-	-	Fab Closure	N/A	MMT	
6V40277DCGI8	-	-	Fab Closure	N/A	MMT	
6V90019DVGI	-	-	Fab closure	N/A	MMT	
6V90019DVGI8	-	-	Fab closure	N/A	MMT	
72401L10DB	-	-	Fab Closure	N/A	SPO	
72401L10P	-	-	Fab Closure	N/A	SPO	
72401L10PDG	-	-	Fab Closure	N/A	SPO	
72401L10SO	-	-	Fab Closure	N/A	SPO	
72401L10SO8	-	-	Fab Closure	N/A	SPO	
72401L15DB	-	-	Fab Closure	N/A	SPO	
72401L15P	-	-	Fab Closure	N/A	SPO	
72401L15SO	-	-	Fab Closure	N/A	SPO	
72401L15SO8	-	-	Fab Closure	N/A	SPO	
72401L25DB	-	-	Fab Closure	N/A	SPO	
72401L25P	-	-	Fab Closure	N/A	SPO	
72401L25SO	-	-	Fab Closure	N/A	SPO	
72401L25SO8	-	-	Fab Closure	N/A	SPO	
72401L35DB	-	-	Fab Closure	N/A	SPO	
72401L35P	-	-	Fab Closure	N/A	SPO	
72401L35SO	-	-	Fab Closure	N/A	SPO	
72401L35SO8	-	-	Fab Closure	N/A	SPO	
72401L45DB	-	-	Fab Closure	N/A	SPO	



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Reason for Discontinuance	Replacement Part Availability	Product Group	Notes
72401L45P	-	-	Fab Closure	N/A	SPO	
72401L45SO	-	-	Fab Closure	N/A	SPO	
72401L45SO8	-	-	Fab Closure	N/A	SPO	
72401L45SOG	-	-	Fab Closure	N/A	SPO	
72401L45SOG8	-	-	Fab Closure	N/A	SPO	
72403L10DB	-	-	Fab Closure	N/A	SPO	
72403L10P	-	-	Fab Closure	N/A	SPO	
72403L10SO	-	-	Fab Closure	N/A	SPO	
72403L10SO8	-	-	Fab Closure	N/A	SPO	
72403L15DB	-	-	Fab Closure	N/A	SPO	
72403L15P	-	-	Fab Closure	N/A	SPO	
72403L15SO	-	-	Fab Closure	N/A	SPO	
72403L15SO8	-	-	Fab Closure	N/A	SPO	
72403L25DB	-	-	Fab Closure	N/A	SPO	
72403L25P	-	-	Fab Closure	N/A	SPO	
72403L25SO	-	-	Fab Closure	N/A	SPO	
72403L25SO8	-	-	Fab Closure	N/A	SPO	
72403L35DB	-	-	Fab Closure	N/A	SPO	
72403L35P	-	-	Fab Closure	N/A	SPO	
72403L35SO	-	-	Fab Closure	N/A	SPO	
72403L35SO8	-	-	Fab Closure	N/A	SPO	
72403L45DB	-	-	Fab Closure	N/A	SPO	
72403L45P	-	-	Fab Closure	N/A	SPO	
72403L45SO	-	-	Fab Closure	N/A	SPO	
72403L45SO8	-	-	Fab Closure	N/A	SPO	
72403L45SOG	-	-	Fab Closure	N/A	SPO	
72403L45SOG8	-	-	Fab Closure	N/A	SPO	
72404L15DB	-	-	Fab Closure	N/A	SPO	
72404L45DB	-	-	Fab Closure	N/A	SPO	
728MLF	-	-	Fab Closure	N/A	MMT	
728MLFT	-	-	Fab Closure	N/A	MMT	
72V70840DAG	-	-	Manufacturing Discontinuance	N/A	NWC	
72V70840DAG8	-	-	Manufacturing Discontinuance	N/A	NWC	
72V71623DAG	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
72V71623DAG8	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
72V71643BCG	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
72V71643BCG8	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
72V71643DAG	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
72V71643DAG8	-	-	Manufacturing Discontinuance	N/A	NWC	Note 2
74ALVCF162835APAG	-	-	Fab closure	N/A	MIP	
74ALVCF162835APAG8	-	-	Fab closure	N/A	MIP	
74SSTU32864BFG	SSTUA32864BHLF	-	Fab closure	Now	MIP	
74SSTU32864BFG8	SSTUA32864BHLF8	-	Fab closure	Now	MIP	
74SSTU32864CBFG	SSTUA32864BHLF	-	Fab closure	Now	MIP	



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Reason for Discontinuance	Replacement Part Availability	Product Group	Notes
74SSTU32864CBFG8	SSTUA32864BHFL8	-	Fab closure	Now	MIP	
74SSTU32864GBFG	SSTUA32864BHFL	-	Fab closure	Now	MIP	
74SSTU32864GBFG8	SSTUA32864BHFL8	-	Fab closure	Now	MIP	
74SSTUA32866BFG	74SSTUBF32866BBFG	-	Fab closure	Now	MIP	
74SSTUA32866BFG8	74SSTUBF32866BBFG8	-	Fab closure	Now	MIP	
74SSTV16859NLG	SSTVA16859CKLF	-	Fab closure	Now	MIP	
74SSTV16859NLG8	SSTVA16859CKLFT	-	Fab closure	Now	MIP	
74SSTVF16859NLG	SSTVA16859CKLF	-	Fab closure	Now	MIP	
74SSTVF16859NLG8	SSTVA16859CKLFT	-	Fab closure	Now	MIP	
9179AF-12LF	-	-	Fab Closure	N/A	MMT	
9179AF-12LFT	-	-	Fab Closure	N/A	MMT	
9179AM-12LF	-	-	Fab Closure	N/A	MMT	
9179AM-12LFT	-	-	Fab Closure	N/A	MMT	
9250BF-27LF	-	-	Fab Closure	N/A	MMT	
9250BF-27LFT	-	-	Fab Closure	N/A	MMT	
9250BFI-27LF	-	-	Fab Closure	N/A	MMT	
9250BFI-27LFT	-	-	Fab Closure	N/A	MMT	
950811AFLF	-	-	Fab Closure	N/A	MMT	
950811AFLFT	-	-	Fab Closure	N/A	MMT	
950811AGLF	-	-	Fab Closure	N/A	MMT	
950811AGLFT	-	-	Fab Closure	N/A	MMT	
98ULPA877FHLF	98ULPA877AHLF	-	Fab closure	Now	MIP	
98ULPA877FHLF8	98ULPA877AHLF8	-	Fab closure	Now	MIP	
CSP2510DPGG	2510CGLF	-	Fab closure	Now	MIP	
CSP2510DPGG8	2510CGLFT	-	Fab closure	Now	MIP	
CSP2510DPGGI	-	2510CGLF	Fab closure	Now	MIP	
CSP2510DPGGI8	-	2510CGLFT	Fab closure	Now	MIP	
CSPT855PGG	93V855AGLF	-	Fab closure	Now	MIP	
CSPT855PGG8	93V855AGLFT	-	Fab closure	Now	MIP	
CSPT855PGGI	-	93V855AGLF	Fab closure	Now	MIP	
CSPT855PGGI8	-	93V855AGLFT	Fab closure	Now	MIP	
CSPT857CNLG	95V857AKLF	-	Fab closure	Now	MIP	
CSPT857CNLG8	95V857AKLFT	-	Fab closure	Now	MIP	
CSPT857CPAG	95V857AGLF	-	Fab closure	Now	MIP	
CSPT857CPAG8	95V857AGLFT	-	Fab closure	Now	MIP	
CSPT857DPAG	95V857AGLF	-	Fab closure	Now	MIP	
CSPT857DPAG8	95V857AGLFT	-	Fab closure	Now	MIP	
CSPU877ANLG	CSPUA877ANLG	-	Fab closure	Now	MIP	
CSPU877ANLG8	CSPUA877ANLG8	-	Fab closure	Now	MIP	
CSPU877BVG	CSPUA877ABVG	-	Fab closure	Now	MIP	
CSPU877BVG8	CSPUA877ABVG8	-	Fab closure	Now	MIP	
MK1491-06SLF	-	-	Fab Closure	N/A	MMT	
MK1491-06SLFTR	-	-	Fab Closure	N/A	MMT	
MK1574-01SILF	-	-	Fab Closure	N/A	MMT	



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Reason for Discontinuance	Replacement Part Availability	Product Group	Notes
MK1574-01SILFTR	-	-	Fab Closure	N/A	MMT	
MK1574-01SLF	-	-	Fab Closure	N/A	MMT	
MK1574-01SLFTR	-	-	Fab Closure	N/A	MMT	
MK1581-01GILF	-	-	Fab Closure	N/A	MMT	
MK1581-01GILFTR	-	-	Fab Closure	N/A	MMT	
MK1704ALF	-	-	Fab Closure	N/A	MMT	
MK1704ALFTR	-	-	Fab Closure	N/A	MMT	
MK1707SILF	-	-	Fab Closure	N/A	MMT	
MK1707SILFTR	-	-	Fab Closure	N/A	MMT	
MK1707SLF	-	-	Fab Closure	N/A	MMT	
MK1707SLFTR	-	-	Fab Closure	N/A	MMT	
MK1709AGLF	-	-	Fab Closure	N/A	MMT	
MK1709AGLFTR	-	-	Fab Closure	N/A	MMT	
MK1709SILF	-	-	Fab Closure	N/A	MMT	
MK1709SILFTR	-	-	Fab Closure	N/A	MMT	
MK1709SLF	-	-	Fab Closure	N/A	MMT	
MK1709SLFTR	-	-	Fab Closure	N/A	MMT	
MK1714-01RILF	-	-	Fab Closure	N/A	MMT	
MK1714-01RILFTR	-	-	Fab Closure	N/A	MMT	
MK1726-01SLF	-	-	Fab Closure	N/A	MMT	
MK1726-01SLFTR	-	-	Fab Closure	N/A	MMT	
MK2049-34SAILF	-	-	Fab Closure	N/A	MMT	
MK2049-34SAILFTR	-	-	Fab Closure	N/A	MMT	
MK2049-36SILF	-	-	Fab Closure	N/A	MMT	
MK2049-36SILFTR	-	-	Fab Closure	N/A	MMT	
MK2772-01SLF	-	-	Fab Closure	N/A	MMT	
MK2772-01SLFTR	-	-	Fab Closure	N/A	MMT	
MK3722GLF	-	-	Fab Closure	N/A	MMT	
MK3722GLFTR	-	-	Fab Closure	N/A	MMT	
MK3727DLF	-	-	Fab Closure	N/A	MMT	
MK3727DLFTR	-	-	Fab Closure	N/A	MMT	
MK3727SLF	-	-	Fab Closure	N/A	MMT	
MK3727SLFTR	-	-	Fab Closure	N/A	MMT	
MK5811ASLF	-	-	Fab Closure	N/A	MMT	
MK5811ASLFTR	-	-	Fab Closure	N/A	MMT	
MK5811ASLFTR-IB0	-	-	Fab Closure	N/A	MMT	
MK5812SLF	-	-	Fab Closure	N/A	MMT	
MK5812SLFTR	-	-	Fab Closure	N/A	MMT	
MPC905EF	83905AMLF	-	Manufacturing Discontinuance	Now	NWC	
MPC905EFR2	83905AMLFT	-	Manufacturing Discontinuance	Now	NWC	
TSI107C-100JE	-	-	Fab Closure	N/A	SPO	
TSI107D-100JE	-	-	Fab Closure	N/A	SPO	
TSI107D-100JEY	-	-	Fab Closure	N/A	SPO	
TSI107D-133LE	-	-	Fab Closure	N/A	SPO	



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Reason for Discontinuance	Replacement Part Availability	Product Group	Notes
TSI107D-133LEY	-	-	Fab Closure	N/A	SPO	
TSI148-133CL	-	-	Fab Closure	N/A	SPO	Note 3
TSI148-133CLY	-	-	Fab Closure	N/A	SPO	Note 3
TSI148-133IL	-	-	Fab Closure	N/A	SPO	Note 3
TSI148-133ILY	-	-	Fab Closure	N/A	SPO	Note 3
TSI381A-66IL	-	-	Manufacturing Discontinuance	N/A	ACP	
TSI381A-66ILV	-	-	Manufacturing Discontinuance	N/A	ACP	
TSI382A-66IL	-	-	Manufacturing Discontinuance	N/A	ACP	
TSI382A-66ILV	-	-	Manufacturing Discontinuance	N/A	ACP	

Special Notes:

1. Limited Quantity available - only 4K
2. Limited Quantity available -only 5K
3. The last time buy date for these parts is June 10, 2015. The last time ship date for these parts is December 31, 2015