

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification Products

Publication Date: 4/28/2017

Revision Description:

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC17019 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
CA3140MZ96S2705	04/28/17	01/28/18	01/28/19	CA3140MZ96
CP80C88	04/28/17	10/28/17	04/28/18	CP80C88Z
CP80C88-2	04/28/17	10/28/17	04/28/18	CP80C88-2Z
CP82C54	04/28/17	10/28/17	04/28/18	CP82C54Z
CP82C55A	04/28/17	10/28/17	04/28/18	CP82C55AZ
CP82C59A	04/28/17	10/28/17	04/28/18	CP82C59AZ
CP82C84A	04/28/17	10/28/17	04/28/18	None
CS82C54	04/28/17	10/28/17	04/28/18	CS82C54Z
CS82C54-10	04/28/17	10/28/17	04/28/18	CS82C54-10Z
CS82C55A	04/28/17	10/28/17	04/28/18	CS82C55AZ
CS82C55AZ96S2705	04/28/17	01/28/18	01/28/19	CS82C55AZ96
EL4543ILZS2714	04/28/17	04/28/18	10/28/18	EL4543ILZ
EL4543ILZ-T7S2714	04/28/17	04/28/18	10/28/18	EL4543ILZ-T7
EL4543IUZS2714	04/28/17	04/28/18	10/28/18	EL4543IUZ
EL4543IUZ-T13S2714	04/28/17	04/28/18	10/28/18	EL4543IUZ-T13
EL7202CN	04/28/17	10/28/17	04/28/18	EL7202CSZ
EL9110IUZE9049	04/28/17	04/28/18	10/28/18	EL9110IUZ
EL9110IUZE9049-T13	04/28/17	04/28/18	10/28/18	EL9110IUZ-T13
EL9110IUZE9049-T7	04/28/17	04/28/18	10/28/18	EL9110IUZ-T7
EL9110IUZS2714	04/28/17	04/28/18	10/28/18	EL9110IUZ
GWS4618L	04/28/17	04/28/17	04/28/17	None
GWS9293	04/28/17	04/28/17	04/28/17	None
GWS9294	04/28/17	04/28/17	04/28/17	None
HA5351W	04/28/17	10/28/17	04/28/18	HFA5351IBZ
HD3-6409-9	04/28/17	10/28/17	04/28/18	CP82C59AZ
HFA1105W	04/28/17	04/28/18	10/28/18	HFA1105IBZ
HIP6004ECBZ	04/28/17	10/28/17	04/28/18	None
HIP6004ECBZ-T	04/28/17	10/28/17	04/28/18	None
HIP6006CVZ-TS2462	04/28/17	04/28/18	10/28/18	None
HSP45102SC-33	04/28/17	10/28/17	04/28/18	HSP45102SC-33Z
ICL7663SACPA	04/28/17	10/28/17	04/28/18	ICL7663SCPAZ
ICM7211AMIM44	04/28/17	10/28/17	04/28/18	ICM7211AMIPLZ
ICM7243BIPLZ	04/28/17	10/28/17	04/28/18	None
ID82C59A	04/28/17	10/28/17	04/28/18	IS82C59AZ
ID82C59A-12	04/28/17	10/28/17	04/28/18	IS82C59A-12Z
IP82C52	04/28/17	10/28/17	04/28/18	CP82C52Z
IP82C54	04/28/17	10/28/17	04/28/18	IP82C54Z
IP82C54-10	04/28/17	10/28/17	04/28/18	IP82C54-10Z
IP82C55A	04/28/17	10/28/17	04/28/18	IP82C55AZ
IS82C37A	04/28/17	10/28/17	04/28/18	None
IS82C52	04/28/17	10/28/17	04/28/18	IS82C52Z
IS82C54	04/28/17	10/28/17	04/28/18	IS82C54Z
IS82C54-10	04/28/17	10/28/17	04/28/18	IS82C54-10Z
IS82C54-1096	04/28/17	10/28/17	04/28/18	IS82C54-10Z96
IS82C5496	04/28/17	10/28/17	04/28/18	IS82C54Z96

Exact Intersil Part # No other variation is being impacted.	Notice PLC17019 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
IS82C55A	04/28/17	10/28/17	04/28/18	IS82C55AZ
IS82C55A-5	04/28/17	10/28/17	04/28/18	IS82C55A-5Z
IS82C59A	04/28/17	10/28/17	04/28/18	IS82C59AZ
IS82C59A-12	04/28/17	10/28/17	04/28/18	IS82C59A-12Z
IS82C59A-12X96	04/28/17	10/28/17	04/28/18	IS82C59A-12Z96
ISL12027IBZ-EVAL	04/28/17	04/28/18	10/28/18	None
ISL1557AIRZ-T7S2705	04/28/17	01/28/18	01/28/19	ISL1557AIRZ-T7
ISL22313UFU10Z	04/28/17	10/28/17	04/28/18	None
ISL22313UFU10Z-TK	04/28/17	10/28/17	04/28/18	None
ISL22313WUFU10Z	04/28/17	10/28/17	04/28/18	None
ISL22313WUFU10Z-TK	04/28/17	10/28/17	04/28/18	None
ISL29001IROZ	04/28/17	10/28/17	04/28/18	ISL29023IROZ, ISL29035IROZ
ISL29001IROZ-T7	04/28/17	10/28/17	04/28/18	ISL29023IROZ, ISL29035IROZ
ISL29003IROZ	04/28/17	10/28/17	04/28/18	ISL29023IROZ, ISL29035IROZ
ISL29003IROZ-EVALZ	04/28/17	10/28/17	04/28/18	ISL29023IROZ-EVALZ, ISL29035IROZ-EVALZ
ISL29003IROZ-T7	04/28/17	10/28/17	04/28/18	ISL29023IROZ, ISL29035IROZ
ISL29018IROZ-EVALZ	04/28/17	10/28/17	04/28/18	ISL29028AIROZ-EVALZ
ISL29018IROZ-T7	04/28/17	10/28/17	04/28/18	ISL29028AIROZ-T7
ISL29018IROZ-T7S2722	04/28/17	04/28/18	10/28/18	ISL29028AIROZ-T7
ISL29018IROZ-T7S2723	04/28/17	04/28/18	10/28/18	ISL29028AIROZ-T7
ISL29028IROZ-T7R5484	04/28/17	10/28/17	04/28/18	ISL29028AIROZ-T7
ISL29030IROZ-EVALZ	04/28/17	10/28/17	04/28/18	ISL29030AIROZ-EVALZ
ISL29030IROZ-T7	04/28/17	10/28/17	04/28/18	ISL29030AIROZ-T7
ISL29030IROZ-T7R5430	04/28/17	04/28/18	10/28/18	ISL29030AIROZ-T7
ISL29030IROZ-T7S2426	04/28/17	04/28/18	10/28/18	ISL29030AIROZ-T7
ISL29038IROZ-T7S2722	04/28/17	04/28/18	10/28/18	ISL29038IROZ-T7
ISL29043IROMZ-EVALZ	04/28/17	10/28/17	04/28/18	ISL29044AIROMZ-EVALZ
ISL29043IROMZ-T7	04/28/17	10/28/17	04/28/18	ISL29044AIROMZ-T7
ISL29044IROMZ-EVALZ	04/28/17	10/28/17	04/28/18	ISL29044AIROMZ-EVALZ
ISL29044IROMZ-T7	04/28/17	10/28/17	04/28/18	ISL29044AIROMZ-T7
ISL43110IBZ	04/28/17	10/28/17	04/28/18	ISL43110IHZ-T
ISL43110IBZ-T	04/28/17	10/28/17	04/28/18	ISL43110IHZ-T
ISL43111IBZ	04/28/17	10/28/17	04/28/18	ISL43111IHZ-T
ISL43111IBZ-T	04/28/17	10/28/17	04/28/18	ISL43111IHZ-T
ISL43112IBZ	04/28/17	10/28/17	04/28/18	ISL43112IHZ-T
ISL43112IBZ-T	04/28/17	10/28/17	04/28/18	ISL43112IHZ-T
ISL43113IBZ	04/28/17	10/28/17	04/28/18	ISL43113IHZ-T
ISL43113IBZ-T	04/28/17	10/28/17	04/28/18	ISL43113IHZ-T
ISL43141WR5435	04/28/17	04/28/18	10/28/18	None
ISL43141WR5472	04/28/17	04/28/18	10/28/18	None
ISL43143IVZ	04/28/17	10/28/17	04/28/18	None
ISL43143IVZ-T	04/28/17	10/28/17	04/28/18	None
ISL43145IVZ	04/28/17	10/28/17	04/28/18	None
ISL43145IVZ-T	04/28/17	10/28/17	04/28/18	None
ISL43681WR5345	04/28/17	04/28/18	10/28/18	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC17019 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL5120IHZ-T	04/28/17	10/28/17	04/28/18	None
ISL54051IHZ-T	04/28/17	10/28/17	04/28/18	None
ISL54051IRUZ-T	04/28/17	10/28/17	04/28/18	None
ISL55033IRTZT13S2490	04/28/17	04/28/18	10/28/18	ISL55033IRTZ-T13
ISL6119HIBZA	04/28/17	10/28/17	04/28/18	None
ISL6119HIBZA-T	04/28/17	10/28/17	04/28/18	None
ISL6119LIBZA	04/28/17	10/28/17	04/28/18	None
ISL6119LIBZA-T	04/28/17	10/28/17	04/28/18	None
ISL6401CBZ	04/28/17	10/28/17	04/28/18	None
ISL6401CBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6520AIBZ	04/28/17	10/28/17	04/28/18	None
ISL6520AIBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6520BCBZ	04/28/17	10/28/17	04/28/18	None
ISL6520BCBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6522BIBZ	04/28/17	10/28/17	04/28/18	None
ISL6522BIBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6522CBZ	04/28/17	10/28/17	04/28/18	None
ISL6522CBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6522CBZ-TR5190	04/28/17	10/28/17	04/28/18	None
ISL6522CBZ-TR5190C	04/28/17	01/28/18	01/28/19	None
ISL6522IBZ	04/28/17	10/28/17	04/28/18	None
ISL6522IBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6524CBZ	04/28/17	10/28/17	04/28/18	None
ISL6524CBZA	04/28/17	10/28/17	04/28/18	None
ISL6524CBZA-T	04/28/17	10/28/17	04/28/18	None
ISL6524CBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6525CBZ	04/28/17	10/28/17	04/28/18	None
ISL6525CBZ-T	04/28/17	10/28/17	04/28/18	None
ISL6551IBZ	04/28/17	10/28/17	04/28/18	ISL6754AAZA
ISL6551IBZ-T	04/28/17	10/28/17	04/28/18	ISL6754AAZA-T
ISL8273MBIRZ	04/28/17	10/28/17	04/28/18	ISL8273MAIRZ
ISL8273MBIRZ-T	04/28/17	10/28/17	04/28/18	ISL8273MAIRZ-T
ISL8323IBZ	04/28/17	10/28/17	04/28/18	None
ISL8323IBZ-T	04/28/17	10/28/17	04/28/18	None
ISL8391IBZ	04/28/17	10/28/17	04/28/18	None
ISL8391IBZ-T	04/28/17	10/28/17	04/28/18	None
ISL8393IBZ	04/28/17	10/28/17	04/28/18	None
ISL8393IBZ-T	04/28/17	10/28/17	04/28/18	None
ISL84514IBZ	04/28/17	10/28/17	04/28/18	ISL84514IHZ-T
ISL84514IBZ-T	04/28/17	10/28/17	04/28/18	ISL84514IHZ-T
ISL84515IBZ	04/28/17	10/28/17	04/28/18	ISL84515IHZ-T
ISL84515IBZ-T	04/28/17	10/28/17	04/28/18	ISL84515IHZ-T
ISL84516IBZ	04/28/17	10/28/17	04/28/18	ISL84516IHZ-T
ISL84516IBZ-T	04/28/17	10/28/17	04/28/18	ISL84516IHZ-T
ISL84517IBZ	04/28/17	10/28/17	04/28/18	ISL84517IHZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC17019 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL84517IBZ-T	04/28/17	10/28/17	04/28/18	ISL84517IHZ-T
ISL84541CBZ	04/28/17	10/28/17	04/28/18	ISL84541IBZ
ISL84541CBZ-T	04/28/17	10/28/17	04/28/18	ISL84541IBZ-T
ISL84544CBZ	04/28/17	10/28/17	04/28/18	ISL84544IHZ-T
ISL84544CBZ-T	04/28/17	10/28/17	04/28/18	ISL84544IHZ-T
ISL8484IRZ	04/28/17	10/28/17	04/28/18	ISL8484IUZ
ISL8484IRZ-T	04/28/17	10/28/17	04/28/18	ISL8484IUZ-T
ISL90726WIE627Z-TK	04/28/17	10/28/17	04/28/18	ISL90727WIE627Z-TK
ISL9110AITAZ-TS2765	04/28/17	04/28/18	10/28/18	None
TW9910-LA2-GR	04/28/17	10/28/17	04/28/18	TW9910-NA2-GR
TW9910-LB2-GR	04/28/17	10/28/17	04/28/18	TW9910-NB2-GR
X28HC256JI-12	04/28/17	10/28/17	04/28/18	X28HC256JIZ-12
X28HC256JI-15	04/28/17	10/28/17	04/28/18	X28HC256JIZ-15
X28HC256SI-12	04/28/17	10/28/17	04/28/18	X28HC256SIZ-12
X28HC256SI-90	04/28/17	10/28/17	04/28/18	X28HC256SIZ-90
X28HC256WC6721	04/28/17	04/28/18	10/28/18	X28HC256W
X9511WPIZ	04/28/17	10/28/17	04/28/18	X9511WSIZ
X9511WPZ	04/28/17	10/28/17	04/28/18	X9511WSZ